

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-27198
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER INJECTOR	7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 18
2. Name of Operator SHELL WESTERN E&P INC.	8. Well No. 242
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	9. Pool name or Wildcat HOBBS (G/SA)
4. Well Location Unit Letter <u>N</u> : <u>1200</u> Feet From The <u>SOUTH</u> Line and <u>2600</u> Feet From The <u>WEST</u> Line Section <u>18</u> Township <u>18S</u> Range <u>38E</u> NMPM LEA County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3665.39' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: <u>Inj Profile Correction</u> ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-10 to 10-18-89:

POH w/inj equip. CO to 4382' (tagged btm). Set CIBP @ 4314' & capped w/1/2 sk cmt. Acid SA perfs 4222' - 4302' w/3000 gals 15% NEFE HCl + 1000# rock salt. Flushed to fm. Tagged @ 4256'. Wshd dwn to 4310'. Set CIBP @ 4168' & capped w/1/2 sk cmt. Set CICR @ 4100'. Sqzd SA perfs 4150' - 58' w/100 sx Cls "C" cmt + 200 SCF N₂/bbl followed by 125 SX Cls "C" cmt + 2% CaCl₂. DO cmt (& CICR @ 4100') 4094' to 4160'. Pres tstd sqz to 500#, held. Drid on CIBP @ 4168' & pushed remnants to 4309'. Installed inj equip, setting Guit Uni-Pkr VI @ 4069'. Pres tstd csq to 500# for 30 min. Retd to inj.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. SMITHERMAN TITLE REGULATORY SUPV. DATE 11-17-89
TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

NOV 21 1989

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: