

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-27243
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTOR	7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 28
2. Name of Operator Shell Western E&P Inc.	8. Well No. 422
3. Address of Operator P.O. Box 576 Houston, TX 77001-0576 (check 4465)	9. Pool name or Wildcat HOBBS (G/SA)
4. Well Location Unit Letter <u>H</u> : <u>2199</u> Feet From The <u>NORTH</u> Line and <u>772</u> Feet From The <u>EAST</u> Line Section <u>28</u> Township <u>18S</u> Range <u>38E</u> NMPM LEA County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3635.12' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: PERF & AT <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-25 TO 6-01-93:

REL PKR & POH W/INJ EQMT. CO TO PBTD @ 4400'. PERF SA 4162' - 4214' (1 SPF). SET RBP @ 4290'. AT PERFS 4239-68' W/1000 GAL 15% HCL. REL RBP & RESET @ 4235'. AT PERFS 4162' - 4214' W/2500 GAL 15% HCL + 1700# ROCK SALT. REL RBP & POH. INST INJ EQMT, SETTING GUIB UNI-VI PKR @ 4145'. PT TBG/CSG ANN TO 500# FOR 30 MIN, HELD. RTI.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. L. Morris TITLE TECH. MANAGER - ASSET ADMIN. DATE 7/27/93
TYPE OR PRINT NAME J. L. MORRIS TELEPHONE NO. 713/544-3797

(This space for State Use)

Orig. Signed by
Paul Raton
Geologist

APPROVED BY _____ TITLE _____ DATE AUG 03 1993

CONDITIONS OF APPROVAL, IF ANY: