

HARVEY E. YATES COMPANY

State HS #1

1980' FSL & 1980' FWL

Sec. 9, T18S, R34E,

Lea County, New Mexico

1/29/91 Sqz cuts @ 8051' w/200 sks Cl "H"+ & 90 sks Cl "H"
Neat to 4000#
2/1/91 Drl out sqz
2/2/91 Abrasa jet cuts @ 8045'; Jet w/1000 gals 15% NEFE
2/5/91 Acdz w/100 gals 15% NEFE
2/7/91 Acdz w/100 gals 15% NEFE
2/8/91 Acdz w/200 gals 15% NEFE
2/12/91 Acdz w/1000 gals 20% NEFE & 500# rock salt
2/16/91 Set retainer @ 8049' & sqz previously perf'd
interval 8054-58' w/300 sks Cl "H"
2/17/91 Re-sqz same interval w/30 sks Cl "H"; Communicated &
sqz'd 8045' cuts
2/19/91 Abrasa jet cuts @ 8045' & wash w/1000 gals 20% NEFE
3/26/91 Set retainer @ 7990' & sqz cuts 8045' w/80 sks Cl "H"
3/28/91 Drl out & test to 1500#-Held ok; Clean out to 8200'
4/2/91 Csg parted
4/3/91 POOH w/5 1/2" csg; GIH & dress off csg
4/5/91 GIH w/8 5/8" x 7" collar, 12'-7" slip jt, 5 1/2" slip
collar on 5 1/2" csg; Cut w/110 sks Cl "C" w/2% CaCl
4/6/91 Drl out cmt & dress off inside of tie in & test to 500#
for 30 min-Held ok
4/9/91 Perf 8082-84' & 8144 1/2' (9 holes)
4/10/91 Acdz w/200 gals 15% NEFE
4/11/91 Acdz w/500 gals 15% NEFE
4/15/91 Run SN to 8174' w/TAC @ 7957'; Run pmp & rods & hang on
production.