## Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

	Kevised 1-1-89
. 51.110	<del> </del>

1.0. box 2000		30-025-27387	
DISTRICT II Santa Fe, New Mexico P.O. Drawer DD, Artesia, NM 88210	o 87504-2088	5. Indicate Type of Lease STATE X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		6. State Oil & Gas Lease No.  L-6309	
SUNDRY NOTICES AND REPORTS ON WI	FIIS		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPE DIFFERENT RESERVOR. USE *APPLICATION FOR P (FORM C-101) FOR SUCH PROPOSALS.)	EN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name	
1. Type of Well:  OB. OAS  WELL X WELL OTHER		State HS	
2. Name of Operator		8. Well No.	
Harvey E. Yates Company		1	
3. Address of Operator		9. Pool name or Wildcat	
P.O. Box 1933, Roswell, New Mexico 88202		West Vacuum Bone Spring	
Unit Letter K: 1980 Feet From The South	Line and 1980	Feet From The West Line	
Section 9 Township 185	Range 34E	NMPM Lea County	
10. Elevation (Show whath $4047.5 G1$	her DF, RKB, RT, GR, eic.) L		
11. Check Appropriate Box to Indicat		Report, or Other Data	
NOTICE OF INTENTION TO:		BSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLIN	IG OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CASING TEST AND C		
OTHER:	OTHER: Addition	nal Squeezing & testing additiona zones	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details work) SEE RULE 1103.	s, and give persinent dates, incl	uding estimated date of starting any proposed	
12-5-90. Squeeze Wolfcamp perfs 10854-1100	4'. Cement retain	ner @ 10800'. Squeeze w/875 sks (	
to "H" to 3000#. Left 35' cmt on t	op of Retainer,	new PBTD @ 10755'.	
12-7-90'			
12 0 00 Porf 0040-66! (27 Holes) and 1005	4-58' (9 Holes).	Acidize w/2500 gals 20% NEFE.	
12-13-90 Set cement retainer @ 9890', squeeze perfs 9940-10058 w/ 200 sks C1 "H" to 5000#			
12-14-90 Perf 9274-36' (25 Holes) Acidize	w/200 gals 20% N	EFE.	
12-16-90 Acidize w/2300 gals 20% NEFE			
12-18-90 Acidize w/4000 gals 20% NEFE & 40	000 gals O.F.	- 405 - 1 - 03 Hull to 4000	
12-18-90 ACIdize W/4000 gais 20% NHTB & 10 12-20-90 Squeeze perfs 9274-86', cement re	etainer @ 9225'.	Squeeze w/85 sks C1 "H" to 4000	
12-22-90 Abras Jet 2 cuts @ 8051'. Wash w	v/500 gals 20% NE	FE & Squeeze W/200 gars.	
12-28-90 Run SN to 8109' and Anchor @ 7951	l'.		
12-29-90 Ran pump and rods. Hang on produ	action 3:00 PM.		
I hereby certify that the information above is true and complete to the best of my knowledg	e and belief.		
1. Toller		oduction Manager 1/8/91	
SKIRATURE	- IIILE	TELEPHIONE NO. 623-6601	
TYPE OR PRINT NAME Ray F. Nokes		TELEPTENE NO. 020 0002	
(This space for State Use)			
	- тп.е	DATE	
APPROVED DY	- 11114	2	
CONDITIONS OF APPROVAL, IF ANY:			