

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-2229	
7. Unit Agreement Name	
SMGSAU	
8. Farm or Lease Name	
TRACT 4	
9. Well No.	
11	
10. Field and Pool, or Wildcat	
MALJAMAR (G-SA)	
12. County	
LEA	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	2. Name of Operator
	<i>Company</i> <b>CITIES SERVICE OIL &amp; GAS CORPORATION</b>
3. Address of Operator	
	<b>P. O. Box 1919 - Midland, Texas 79702</b>
4. Location of Well	
UNIT LETTER <b>E</b> , <b>1345</b> FEET FROM THE <b>North</b> LINE AND <b>100</b> FEET FROM THE <b>West</b> LINE, SECTION <b>29</b> TOWNSHIP <b>17S</b> RANGE <b>33E</b> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
<b>4077' GR</b>	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

OTD 4072'. It is proposed to plug and abandon this well in the following manner:

1. MIRU Pulling unit, NU BOP, RU WL. RIH w/blanking plug to 3812'. POOH w/wl.
2. Release tbg. and spot a 30 sack cmt. plug on top of pkr. POOH to approximately 3500'. CHC. POOH to approximately 2900' and spot a 30 sack cmt. plug across the base of the salt.
3. POOH to approximately 1450' and spot a 50 sack cmt. plug across the top of csg. shoe and top of salt. POOH.
4. POOH to approximately 200' and spot a 20 sack cmt. plug to surface. POOH.
5. ND BOP. CO WH. Install a dry hole marker to designate a plugged and abandoned location.

THE COMMISSION MUST BE NOTIFIED 72 HOURS PRIOR TO THE BEGINNING OF PLUGGING OR OTHER WORK FOR THE WELL.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *E. L. Sexton* TITLE REG. OPER. MGR. - PROD. DATE 4-19-83

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE APR 25 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
APR 22 1983  
HOBBS OFFICE