

NEW MEXICO OIL CONSERVATION COMMISSION

5a. Indicate Type of Lease

State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

OF USE THIS FORM FOR PROPOSALS TO DRILL OR TO PLUG OR TO PLUG BACK TO A DIFFERENT RESERVOIR.
SEE APPLICATION FOR PLUG BACK (FORM C-103) FOR PLUG BACK PROPOSALS.

7. Unit Agreement Name

8. Form of Lease Name
SPEIGHT 'A'

9. Well No.
1

10. Field and Pool, or Wildcat

S. Carter San Andres

12. County

Lea

15. Elevation (Show whether DF, RT, GR, etc.)

3670' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

SUBSEQUENT REPORT OF:

NOTICE OF INTENTION TO:

REMEDIAL WORK ☐
PLUG AND ABANDON ☐
CHANGE PLANS ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed operations.)
SEE RULE 1103.

Propose to plug and abandon subject well as follows:

- (1) Set CIBP with 35' cement on top at 5150'. Displace hole with mud (10# brine-25# SAH Gel/Bbl.)
- (2) Spot 100' plug (cement) with 50' in and 50' out at top of 5 1/2" cutoff. Wait 6 hours and tag plug.
- (3) Spot 100' cement plug with 50' in and 50' out at bottom of 8 5/8" (398') WOC for 6 hours and tag plug
- (4) Spot 10 sacks cement plug at surface and install dry hole marker.

Work should start within next 6 weeks and OCD will be notified 24 hours prior to setting first plug.

I certify that the information above is true and complete to the best of my knowledge and belief.

TITLE **Agent**

DATE **4/5/82**

ORIGINAL SIGNATURE

JERRY BOYLE

TITLE

DATE **APR 16 1982**

INSTRUCTIONS OF APPROVAL, IF ANY: