

LG-7137

STANDARD TEST METHOD AND REPORTING GUIDE

Harvey E. Yates Company

P. O. Box 1933, Roswell, New Mexico 88201

S.E. Airstrip

1

Scharb

N 660 South 1980
West 31 18S 35E

3942.0' GR

Lea

Check Appropriate Box To Indicate Nature of Sample, Report, or Other Data

1. NATURE OF INFORMATION TO:

PLUG AND ABANDON	OTHER	PLUG AND ABANDON
CHANGE PLANS	OTHER	PLUG AND ABANDON

- 1/3/82 Day 1, Operation - WOC, Depth - 427', Progress - 427', Formation - Red Bed & Surf rock. Dev - 1/4" @ 427'. SPUDDED @ 8:00 a.m. 1/2/82. Ran 12 jts (431') 13 3/8" ST&C H-40 48# csg. Shoe @ 427', FC @ 402' Cmtd w/425 sx Class C plus 2% CaCl. Plug down @ 11:15 p. m. 1/2/82. Circ 50 sx to pit.
- 1/4/82 Day 2, Operation - Fishing, Depth - 535', Progress - 108', Formation - Red Bed. MW-9.5#, Vis-32, pH-8, Cl-8000. Drlg-3 hrs, Trips-1 hr, NU & drlg cmt 11 hrs, Fishing 8 hrs. WOC 18 hrs tested 13 3/8" csg w/500 psi-30 min. Held ok.
- 1/10/82 Operation - WOC, Depth -3990', Progress - 0', Formation - li. Ran 41 jts 32# J-55 ST&C (1770') 8 5/8" csg. Ran 55 jts 8 5/8" 24# J-55 ST&C (2218') csg. Shoe set @ 3990', FC @ 3946'. Cem w/1600 sx Halliburton lite w/12# salt, 3# Gilsonite, 1/4# floccle. Followed w/200 sx Class "C" w/2% CaCl. PD @ 3:15 p. m. Circ 200 sx to pit.
- 1/11/82 Day 9, Operation - drlg, Depth - 4415', Progress - 525'. formation - li, WOC 18 hrs. Tested csg w/1500 psi. 30 min O.K.

I, the undersigned, certify that the above information is true and complete to the best of my knowledge and belief.

Paul J. Hardee

Engineer

DATE 1/13/82

LONG TERM OF APPROVAL OF TEST