Submit 3 Copies to Appropriate District Office

State of New Mexico ...nergy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

District Office			
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION		WELL API NO.
DISTRICT II	P.O. Box 208 Santa Fe, New Mexico		30-025-27695
P.O. Drawer DD, Artesia, NM 88210	Summa 1 C, 146W MICKICO	0150 4 -2000	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No. L-786
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESER	CES AND REPORTS ON WEL POSALS TO DRILL OR TO DEEPEN VOIR. USE "APPLICATION FOR PEI 101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL WELL	Dry-H		
2. Name of Operator	OHER SWD C	andidate	Gulf State 8. Well No.
Bledsoe Petro Corpora	tion		8. Well No. 5
3. Address of Operator			9. Pool name or Wildcat
3908 N. Peniel, Suite 4. Well Location	500, Bethany, OK 7300	8	Buckeye Abo
Unit LetterF :165	O Feet From The North	Line and 165	O Feet From The West Line
Section 9	Township 18S Ra	nge 35E	NMPM Lea County
	10. Elevation (Show whether	DF, RKB, RT, GR, etc.)	
11. Check A	Appropriate Box to Indicate N	Nature of Notice R	eport or Other Data
NOTICE OF INT		·	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	
PULL OR ALTER CASING		CASING TEST AND CE	
OTHER:	· · · · · · · · · · · · · · · · · · ·		
12. Describe Proposed or Completed Operati		<u> </u>	
work) SEE RULE 1103. See Attached Plugging	Report		
	•		
	•		
	(
I hereby certify that the information above is true	and complete to the best of my knowledge and	belief.	
SIGNATURE SIGNATURE	11/11/11/11/11/11/m	_E Agent	DATE 01/07/93
TYPEOR PRINT NAME Lynnette Ma	angum		ТЕЦЕРНЮКЕ NO 817 - 629 - 85
(This space for State Use)			3 ·
AFTROVED BY	maner Ciff	OLL& GAS	DATE JAN 1 1 1993
CONDITIONS OF AFFROVAL, IF ANY:			

Plugging Report

Gulf State #5, Lea County, New Mexico Bledsoe Petroleum Corporation

Plugging Con	tractor: Star Well Service, Inc., P. O. Box 1064 Eastland, Texas Phone: 817-629-8563
10/28/92	Notify NM OCC. Move rig and equipment to location. Rig up. Set CIBP at 8500'. Dump 5 sx cement on plug. Load hole. Run bond log. SDFN
10/29/92	Weld on pull nipple. Rig up casing jacks. Work stretch in casing. Cut casing at 3655'. Lay down casing. Install B.O.P. and run 80 jts. tubing. SDFN

10/30/92 Run 38 its. tubing. Tag casing stub. Trying to get in stub. SDFN

11/02/92 Circulate tubing trying to get into stub. SDFN

Got tubing to 3708'. Pumped 75 sx Cl. A cement. Pull 11/03/92 tubing . WOC 4 hrs. Tag plug at 3506'. Pull tubing to 1000'. Pump 30 sx Cl. A cement . Pull tubing to 30' and pump 10 sx Cl. A cement. Rig down. Cut off casing and heads 3' below G.L. Weld on cap and abandoned well marker. Fill pits and cellar. Clean location for abandonment.