

JENNINGS "A" FEDERAL #4  
LEA COUNTY, NEW MEXICO

4. RIH W/5-1/2" 17# IDG PKR W/RETREIVING HEAD AND SN ON 2-7/8" PRODUCTION TBG TO  $\pm 10718$ . HOWCO SPO 2 BBLS 20% NEFE HCL W/ADDITIVES\* FROM 10718 TO 10632. RAISE PKR SEAT TO  $\pm 10601$ . SET PKR. ND BOP. NU WH. INSTALL WH ISOLATION TOOL. TRAP 1000 PSI CP.
5. HOWCO ACDZ SET II PERFS 10704-718 W/1500 GALS 20% NEFE HCL W/ADDITIVES\* IN ONE STAGE AT 3 BPM. ANTICIPATED TREATING PRESSURE 2500 PSI. MAX PRESSURE 3500 PSI. FLUSH TO BTM PERF W/NE TREATED 2% KCL FRESH WTR.
6. SWAB/FLOW BACK L&W. NU BOP. RLSE PKR. LATCH RBP. POH W/PKR & RBP.
7. RIH W/2-7/8" MA, IERF SUB, SN, 7 JTS 2-7/8" TBG & TAC ON 2-7/8" PRODUCTION TBG. TS  $\pm 10855$ , SN  $\pm 10718$ , TAC  $\pm 10601$ . ND BOP.
8. RIH W/1.5" PUMP C 86 TAPER ROD STRING (NOTE: NO ROD DATA SHEET WAS PREPARED FOLLOWING INITIAL INSTALLATION. ROD TALLY MUST BE PREPARED.) NU WH. RR.
9. PUT WELL ON PRODUCTION TEST AT 1.5x144x7 (PUMP CAPACITY  $\pm 185$  BPD).