

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG 887	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☐ GAS ☐ OTHER ☒ P&A

2. Name of Operator  
Yates Petroleum Corporation

3. Address of Operator  
207 South 4th St., Artesia, NM 88210

4. Location of Well  
UNIT LETTER A 330 FEET FROM THE North LINE AND 660 FEET FROM  
THE East LINE, SECTION 2 TOWNSHIP 18S RANGE 37E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
3695' GR

7. Unit Agreement Name  
8. Farm or Lease Name  
Blarney Stone VS State  
9. Well No.  
1  
10. Field and Pool, or Wildcat  
Und. Lovington Penn  
12. County  
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐  
PLUG AND ABANDON ☐  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:  
REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☒

6. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged well as follows:  
Pulled packer and tubing. Set CIBP at 5400', and capped w/35' cement. Cut 5-1/2" casing at 4400'. Recovered 4250' of 5-1/2" casing.

Plug #1: Spot 30 sack cement at 4300' (across 5-1/2" stub). Tagged cement at 4247'. Spot 25 sack cement plug. PD 8:00 AM 3-25-83. WOC 4 hrs. Tagged cement at 4242'. Spot 35 sack cement plug. PD 12:45 PM 3-25-83. WOC 4 hrs. Tagged cement at 4187'. (116' plug)  
Plug #2: Spot 80 sack cement plug at 3388'. PD 5:55 PM 3-25-83. Tagged cement 3326'. Spot 40 sack cement plug. PD 8:00 AM 3-26-83. Tagged cement at 3149'. (238' plug)  
Plug #3: Spot 35 sack cement plug at 2182'. PD 12:38 PM 3-26-83. (100' plug)  
Plug #4: Spot 35 sack cement plug at 586'. PD 1:12 PM 3-26-83. (100' plug)  
Plug #5: Spot 10 sack cement plug at surface.

Used salt gel mud between plugs. Verbal approval for plugging procedure given by Mr. Eddie Seay, OCD, Hobbs, 3-18-83.

Install dry hole marker and clean location.

7. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Production Supervisor DATE 3-31-83

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE AUG 21 1986

CONDITIONS OF APPROVAL, IF ANY: