State of New Mexico Minerals and Natural Resources Department Ener

Form C-103

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088

Revised 1-1-89

WELL API NO.

P.O. Box 2088	30-025-28072
Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease STATE X FEE
DISTRICT III 000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No. LG-964-3
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
Type of Well: OR. GAS WELL X WELL OTHER	Wood State
Name of Operator	8. Well No.
YATES PETROLEUM CORPORATION	1
Address of Operator	9. Pool name or Wildcat
105 South 4th St., Artesia, NM 88210	Scharb Wolfcamp
N 330 - South	980 Feet From The West Line
Unit Letter N : 330 Feet From The South Line and 1	980 Feet From The West Line
	NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	(//////////////////////////////////////
11. Check Appropriate Box to Indicate Nature of Notice, R	•
NOTICE OF INTENTION TO: SUB	SSEQUENT REPORT OF:
ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT X
ULL OR ALTER CASING CASING TEST AND CI	EMENT JOB
OTHER:OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu	wling assignated data of starting any propaged
work) SEE RULE 1103. 4-17-96 - Moved in and rigged up pulling unit. Picked up with rods. Nippled down wellhead. Nippled up BOP. Relea 2-7/8" tubing. Picked up on rods. POOH with rods. Shut Notified Bonnie w/OCD-Hobbs of commencing plugging operati 4-18-96 - POOH with rest of rods and tubing. Rigged up wi gun and perforated 2 holes at 3350' (top of seating nipple Shut down due to wind and for night. 4-19-96 - POOH with tubing. Rigged up wireline. TIH with and capped with 35' of cement. Rigged down wireline. TIH to load well. Circulate oil into test tank. Shut well in Buddy w/OCD-Hobbs on bridge plug setting. 4-20-22-96 - Pressure tested casing and cement plug to 500 bbls plugging mud from 10300-4000'. POOH with tubing to 9 C cement from 9251-9151' (in 5-1/2" casing). POOH with tu	on rods - rods parted. POOH sed tubing anchor. POOH with well in for night. NOTE: ons. reline. TIH with perforating to drain oil out of tubing). 5-1/2" CIBP and set at 10365' with tubing to 10300'. Attempt for night. NOTE: Notified # for 10 minutes, OK. Spot 146
Thereby certify that the information shows is the and complete to the date of in) and in the Production (
Rusty Klein	TELEPHONE NO. 505/748-14
TYPEOR PRINT NAME RUSE Y RIETH	succession 300, 10 I
(This space for State Use)	DATE JUN 2 1 1996
ABBROVED BY MAN M. FULL TITLE	DATE JUIN I IJJU

CONDITIONS OF APPROVAL, IF JONY: