

**OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

**DISTRICT I**

P.O. Box 1980, Hobbs, NM 88240

**DISTRICT II**

811 S. First Street, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd., Aztec, NM 87410

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG  
BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS)

**1. Type of Well:**

OIL WELL ☒ GAS WELL ☐ OTHER ☐

**2. Name of Operator**

ARROW EXPLORATION COMPANY

**3. Address of Operator**

P.O. BOX 2885

ROSWELL, NEW MEXICO 88202

**4. Well Location**

Unit Letter O : 660 Feet From The SOUTH Line and 1980 Feet From The EAST Line  
Section 26 Township 18S Range 34E NMPM LEA County

**10. Elevation (Show whether DF, RKB, RT, GR, etc.)**

3980' GL

WELL APINO

30-025-28163

**5. Indicate Type of Lease**

STATE ☒

FEE ☐

**6. State Oil & Gas Lease No.**

LG-5188

**7. Lease Name or Unit Agreement Name**

STATE "HQ"

**8. Well No.**

3

**9. Pool Name or Wildcat**

AIRSTRIP

**11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data**

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: TEST QUEEN ZONE ☒

**12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)**

SEE RULE 1103

11/2/95 R.U. COMPUTALOG AND SET CIBP @ 9060', T.I.H. W/ DUMP BAILER AND DUMP 35' OF CEMENT ON TOP OF CIBP. SHUT OFF PERFORATIONS 9124'-9173', CCL INDICATED ROUGH PIPE FROM 9100'-9160'.  
TEST CASING AND PLUG TO 1000 PSI, O.K.

11/3/95 RUN CBL AND PERFORATE 4635'-4639', 4649'-4651', 4666'-76', 4682'-4686', 1 JSPF, 24 SHOTS.

11/4/95 ACIDIZE W/ 1500 GALS. 7 1/2% NEFE ACID AND 48 BALLSEALERS. RATE 3-5 BPM, PRESSURE 2280 PSI TO 4850 PSI, BALLED OUT. ISDP 1750 PSI, 15 MIN. 850 PSI. SWAB BACK LOAD.

11/5/95 R.U. DOWELL AND FRAC WITH 13,250 GALS YF-130 CARRYING 23,600 # 16/30 SAND AND 8,000 # 16/30 SDC SAND, RATE 8 TO 12 BPM, MAX PRESSURE 3099 PSI. ISDP 2390 PSI, 15 MIN. 1781 PSI. SWAB BACK 139 BLW, SHOW OF GAS.

11/6/95 RAN TUBING AND T.A.C, SN @ 4689'.

11/7/95 RAN RODS AND PUMP, STARTED PUMPING @ 11:30 P.M.

11/8/95 RECOVERED 460 B.W., 281 BBLs. OVER LOAD, SHOW OF GAS. CONTINUE TESTING.

11/20/95 FINAL TEST 350 BFW, SHOW OF GAS, IN 24 HOURS, S.I. TO EVALUATE DELAWARE & PENROSE COMPL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bruce A. Stubbs TITLE ENGINEER DATE 11/29/95

TYPE OR PRINT NAME BRUCE A. STUBBS TELEPHONE NO. 505-624-2800

(This space for State Use)

APPROVED BY EXTON TITLE EXTON DATE DEC 6 1995

CONDITIONS OF APPROVAL, IF ANY: