

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

2040 Pacheco St.  
Santa Fe, NM 87505

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-28177
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-1125
7. Lease Name or Unit Agreement Name AMOCO STATE
8. Well No. 1
9. Pool name or Wildcat Mesquite Escarpment Spring

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator SEELY OIL COMPANY	
3. Address of Operator 815 W. 10TH ST.	
4. Well Location Unit Letter H : 1980 Feet From The NORTH Line and 660 Feet From The EAST Line Section 18 Township 18-S Range 34-E NMPM LEA NM County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4072.3 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MRI RU NIPPLE UP BOP RIH W/TBG & 4-3/4 BIT & SCRAPER TO 8600'.
- 2) POOH W/TBG RIH W/5-1/2" CIBP @ 8500' SET IT DESP W/MUD.
- 3) PLUG 1 8500' 25 SXS ON TOP 8500 TOP CMT 8293, PULL TO 5299 SPOT 25 SXS.
- 4) PLUG 2 5299 RU W/L (CUT CSG @ 4567') LAY DOWN 118 JTS 5-1/2".
- 5) RIH W/TBG TO 4617' SPOT 35 SXS ON STUB WOC 3 HRS RIH TAG CMT (4505).
- 6) SPOT 25 SXS 3100' SPOT 25 SXS 1850' SPOT 25 SXS 459 CIRC CMT TO SURFACE.
- 7) CUT WELL HEAD & INSTALL DRY HOLE MARKER.

4-6-00  
Well plugged and abandoned effective 11/19/97  
per [Signature]

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jose A. Gutierrez TITLE P&A SUPERVISOR DATE 11/19/97

TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)

APPROVED BY Johnny Robinson TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

JCT HWW dpo