

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

API# 30-025-28266

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- INJECTOR	7. Unit Agreement Name N. HOBBS (G/SA) UNIT
2. Name of Operator SHELL WESTERN E&P INC.	8. Farm or Lease Name SECTION 32
3. Address of Operator P. O. BOX 991, HOUSTON, TEXAS 77001	9. Well No. 342
4. Location of Well UNIT LETTER 0, 475 FEET FROM THE SOUTH LINE AND 1437 FEET FROM THE EAST LINE, SECTION 32 TOWNSHIP 18-S RANGE 38-E NMPM.	10. Field and Pool, or Wildcat HOBBS (G/SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3625.5' GL, 3635.4' DF	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPWS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER CHECK BRADENHEAD PRESSURE <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PER NMOC DIRECTOR JERRY SEXTON'S REQUEST.

1-06-84: Checked bradenhead pressure - 475#. Rigged up, bled off surface pipe csg pressure slowly for 30 mins - Sweet Gas!! Loaded 8-5/8" csg outside 5-1/2" csg w/20 bbls produced wtr. Pressured up to 500# w/Star Tool pump; could not pump in bradenhead. Pressure bled to 400# in 10 mins.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE JANUARY 12, 1984

ORIGINAL SIGNED BY EDDIE SEAY  
OIL & GAS INSPECTOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE JAN 17 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JAN 16 1984

O.C.D.  
HOBBS OFFICE