

12-18-90 thru 02-22-90

- 1) MIRU PU. NU BOP. TIH w/4-3/4" Kutrite Shoe, 1 jt 4-1/2" WP, jars, 6-3-1/2" DC's & 2-7/8" tbg. Tag @ 8016'.
- 2) Wash over 8016-8046'. TOH. Rec 23' 2-7/8" tbg. TIH w/shoe #2.
- 3) Tag @ 8039'. Cut 8039-8053'. TOH. Rec 11' 2-7/8" tbg. TIH w/shoe #3.
- 4) Cut 8053-8080'. TOH. Rec junk.
- 5) TIH w/shoe #4. Tag @ 8045'. Cut 8045-8056'. Plug shoe. TOH. Rec 17' junk.
- 6) TIH w/shoe #5. Tag @ 7742'. Stuck WP. Jar loose. Work thru tight spt @ 7742'. Tag @ 7778'. Could not work thru.
- 7) TIH w/4-3/4" tapered Kutrite mill. Milled 7742-7746'. TOH. TIH w/shoe #5. Cut 8050-8065'. Pld 35 stands. Rec 13' tbg.
- 8) TIH w/shoe #6. Cut 8064-8068'. TOH. Rec 2' tbg.
- 9) TIH w/shoe #7. Cut 8068-8079'. Lodge fish in WP. Jar loose. TOH. Split shoe.
- 10) TIH w/shoe #8 to 8000'. Cut from 8068-8079'. TOH. Rec 5' junk.
- 11) TIH w/4-11/16" OS. Tag @ 8079'. Latched on. TOH. Rec 10' tbg.
- 12) TIH w/4-1/2" DC's to 8089'. TOH.
- 13) TIH w/shoe #10. Cut 8089-8109'. TOH. Rec 4' tbg.
- 14) TIH w/shoe #11. Cut 8089-8112'. TOH. Rec 18' tbg.
- 15) TIH w/shoe #12. Cut 8112-8124'. TOH. No rec. TIH w/OS. No latch.
- 16) TIH w/OS. Latch on @ 8112'. Jar loose. TOH. Rec 18' tbg.
- 17) TIH w/OS. No latch. TOH.
- 18) TIH w/shoe #13. Cut 8112-8123'. TOH. Rec 11' tbg.
- 19) TIH w/shoe #14. Cut 8123-8135'. TOH. Rec 11' tbg.
- 20) TIH w/shoe #15. Cut 8133-8137'. Plug shoe. TOH. Rec 2' tbg.
- 21) TIH w/shoe #16. Cut 8137-8139'. TOH. No rec. TIH w/4-1/2" DC. Latch on @ 8134'. Jar off. TOH. No rec.
- 22) TIH w/OS. Latch on @ 8137'. Jar off. TOH.
- 23) TIH w/OS to 8000'. S/swell. Part sand line. TOH w/OS. Rec sand line.
- 24) TIH w/OS. S/swell to 7000'. Latch on @ 8137'. TOH. Rec acc 6-3-1/2" DC's.
- 25) TIH w/bit & scraper to 8318'. TOH w/bit.
- 26) TIH w/OS. No latch. TOH. TIH w/shoe, xtra OS to 7500'. Latch on @ 8318'. Jar loose. TOH.
- 27) TIH w/OS. Cir to TOF. Brk cir. Plug shoe. TOH. Rec 60' iron cuttings.
- 28) TIH w/shoe #17 to 7500'. Attmptd to wash over. Plug pipe. TOH. No rec.
- 29) TIH w/shoe #17 to 7500'. Wash to 8318'. Plug shoe. TOH. No rec.
- 30) TIH w/shoe #18 to 8318'. Wash. TOH. No rec.
- 31) TIH w/shoe & hydrostatic bailer. TOH. Rec small cuttings.
- 32) TIH w/OS to 7500'. Dress TOF. Latch on @ 8317'. Jar. TOH. Rec 5' BS.
- 33) TIH w/shoe. Dress TOF. TOH. TIH w/OS. Latch on. Jar. No rec.

(OVER)