Submit & Copies To Appropriate District	State of New Mexico		Form C-103
Office	Energy, Minerals and Natural Resources		Revised March 25, 1999 WELL API NO.
District I 1625 N. French Dr., Hobbs, NM 88240		30-025-28285	
District II OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
811 South First, Artesia, NM 88210 District III 2040 South Pacheco		STATE \(\mathbb{Z}\) FEE \(\mathbb{D}\)	
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
District IV 2040 South Pacheco, Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name:
ODO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FURM C-101) FOR SUCH			Central EK Queen Unit
PROPOSALS.)			
1. Type of Well: Oil Well ☑ Gas Wel ☐ Other			
2. Name of Operator		8. Well No.	
Seely Oil Company			10-1
3. Address of Operator			9. Pool name or Wildcat
815 West 10 th Street, Fort Worth, Texas 76102			EK Yates - Seven Rivers - Queen
4. Well Location			
Unit Letter M : 660 feet from the South line and 330 feet from the West line			
Section 8 Township 18S Range 34E NMPM Lea County			
	10. Elevation (Show whether L		(c.)
4083' GR			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF	INTENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK		REMEDIAL WOR	RK ALTERING CASING
TEMPORARILY ABANDON [☐ CHANGE PLANS ☐	COMMENCE DR	ILLING OPNS. PLUG AND
_		OACING TEST A	ABANDONMENT
PULL OR ALTER CASING [MULTIPLE	CASING TEST A	NU L
	COMPLETION	CENIENT SOB	ļ
OTHER:		OTHER:	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompilation.			
*32			
Seely Oil Company proposes to plug and abandon as set out below:			
Seely Oil Company proposes to plug and abandon as set out below: IF DOMP BAILED 35 THE SPOTTED WIT 86-255X			
Set CIBP @ 4300'. Spot 3 sxs cement on top of plug.			
· · · · · · · · · · · · · · · · · · ·			
• Circulate hole with mud.			
 Spot 25 sxs @ 2930' (base of Salt @ 2880'). Cut and pull casing from 2800'./SPOT 50 /NSINE THE COMMISSION MUST BE NOTIFIED 24 Spot 50 sxs @ 1650' - 1750'. F/1830' +0/65 @DURS, PRIOR TO THE BEGINNING OF Spot 10 sxs @ surface. THIS COVERS T. BISGONG OPERATIONS FOR THE C-103 CSG SHOE. TO BE APPROVED. 			
• Cut and pull casing from 2000 / 5/ 01 05 / 1/ THE COMMISSION MUST BE NOTIFIED 24			
• Spot 50 sxs @ 1650' - 1750'. F//830 70/62 DOURS, PRIOR TO THE BEGINNING OF			
 Spot 10 sxs @ su 	irface. THIS COVERS	T. TO BE APPRO	VED
,	(36 2H0E	. IO DE ATTRO	,
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
() // a/ / a = 5 - 5 - 5 - 5 - 5 - 5 - 5 - 5 - 5 - 5			
SIGNATURE Land	broken TITLE:	Petroleum Eng	lineer DATE: September 10, 2002
 · · · ·			(047) 222 1277
Type or print name: Da	avid L. Henderson		Telephone No: (817) 332-1377
(This space for State use) OC FIELD REPRESENTATIVE II/STAFF MANAGER SEP 26 20			
· · ·	OC FI		
APPROVED BY Lay W. Winb, TITLE DATE DATE DATE OC FIELD REPRESENTATIVE II/STAFF MANAGER TITLE DATE DA			
Conditions of approval, if any:			
—			