

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

NO. OF COPIES DESIRED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.

API #30-025-28411

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO STOP OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> Name of Operator SHELL WESTERN E&P INC. Address of Operator P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435) Location of Well UNIT LETTER <u>M</u> <u>1250</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>185</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>33</u> TOWNSHIP <u>18-S</u> RANGE <u>38-E</u> N.M.P.M. 15. Elevation (Show whether DF, RT, CR, etc.) 3635.1' GL	7. Unit Agreement Name N. HOBBS (G/SA) UNIT 8. Field or Lease Name SECTION 33 9. Well No. 142 10. Field and Pool, or Whom HOBBS (G/SA) 12. County LEA
--	--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PROPOSED REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> FULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> WSO, REPERF'D & ACD <input checked="" type="checkbox"/>
--	--	---	--

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 10-13-86: Pulled prod equip. CO to 4300'. Set CIBP @ 4125'.
- 10-14-86: Set CICR @ 3998'. Sqzd San Andres perms 4068' - 4116' w/100 sx Cls "C" cmt + .2% Halad-4 + 2% CaCl₂ followed by 50 sx Cls "C" cmt + 2% CaCl₂. WOC 24 hrs.
- 10-15-86: Tagged TOC @ 3992'. DO cmt (& CICR @ 3998') to 4052'. Pres tstd prev sqzd perms 4027' - 4040' to 500#, held OK.
- 10-16-86: DO cmt to 4086'. Pres tstd sqzd perms 4068' - 4078' to 500#, held OK. DO cmt to 4125'. Pres tstd sqzd perms 4098' - 4116' to 500#, held OK. DO CIBP @ 4125' & pushed to btm @ 4301'. Perf'd San Andres 4067' - 4078'. (2 JSPF).
- 10-17-86: Acd perms 4067' - 4237' w/4500 gals 15% HCl. Perf'd San Andres 4136' - 4237' (2 JSPF).
- 10-18 to 10-19-86: Acd perms 4067' - 4237' w/2850 gals 15% HCl.

NSL-1749

(CONTINUED ON REVERSE SIDE)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

APPROVED BY J. Curtis A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE FEBRUARY 13, 1987
 ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR
 APPROVED BY _____ TITLE _____ DATE FEB 16 1987

10-20-86: Perf'd San Andres 4136' - 4220' (2 JSPF).

10-21-86: Acd perfs 4136' - 4188' w/1000 gals 15% HCl. Installed prod equip & returned well to prod.

RECEIVED
FEB 21 1987
OCD
HOBBS SERVICE