

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES DESIRED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.B.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form O-103
Revised 12-1-77

5a. Indicate type of lease	
State ☒	Free ☐
5. State Oil & Gas Lease No.	
L-3674	

SUNDARY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO STOP OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT WITH FORM C-101 FOR SUCH PROPOSALS.

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		7. Unit Agreement Name
2. Name of Operator AMOCO PRODUCTION COMPANY		8. Term of Lease Name State HQ
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240		9. Well No. 6
4. Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>26</u> TOWNSHIP <u>18-S</u> RANGE <u>34-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Airstrip Wolfcamp
15. Elevation (Show whether LF, RT, GR, etc.) 3987.4' GL		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <u>complete well in Wolfcamp</u> ☒	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to complete in Wolfcamp as follows:

Drill out DV tool (set at 7297'). Load hole with clean brine and run CBL 5650'-6050', 7100'-7500', 9000'-TD. Perf Wolfcamp 10632'-10750' w/4 JSPF using a 3-1/8" gun. RIH with packer with unloader, set at 10,500' and swab back any load. Acidize Wolfcamp with 12000 gals of 15% NEFE HCL with additives. Tag all acid with Radio active material. Run before and after GR/Temp surveys. Flush to perms with 66 bbls clean brine. Swab back spent acid load and evaluate. POH with packer and tubing. TIH with tubing, tubing anchor, and seating nipple. Land seating nipple at 10765' and set anchor at 10615'. Install rods and pump and evaluate.

O+5-NMOCD,H 1-J. R. Barnett, HOU 21.156 1-F. J. Nash, HOU Rm. 4.206 1-GCC 1-Mesa 1-Bass

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Eddie W. Seay</u>	TITLE <u>Assist. Admin. Analyst</u>	DATE <u>8-22-84</u>
APPROVED BY <u>Oil & Gas Inspector</u>	TITLE	DATE <u>AUG 22 1984</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

AUG 22 1984

COPIES
MOBILE C-101