

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES DESIRED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.B.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form O-103
Revised 12-1-77

SUNDARY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG A WELL IN A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL OIL WELLS FOR SUCH PURPOSES.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	2. Name of Operator <i>Amoco Production Company</i>	3. Address of Operator <i>P.O. Box 68, Hobbs, New Mexico 88240</i>	4. Location of Well UNIT LETTER <i>L</i> <i>1980</i> FEET FROM THE <i>South</i> LINE AND <i>660</i> FEET FROM THE <i>West</i> LINE, SECTION <i>26</i> TOWNSHIP <i>18-S</i> RANGE <i>34-E</i> N.M.P.M.	5. Indicate Type of Well State ☒ Gas ☐	6. State Oil & Gas License No. <i>L-3674</i>	7. Unit Agreement Name	8. Name of Lease Name <i>State HQ</i>	9. Well No. <i>8</i>	10. Field and Pool, or Allotment <i>Airstrip Bone Springs</i>	11. Elevation (Show whether DF, RT, GR, etc.) <i>3994.2' GR</i>	12. County <i>Lea</i>
--	--	---	--	--	---	------------------------	--	-------------------------	--	--	--------------------------

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒
COMMENCE DRILLING OPERATIONS ☐
CASING TEST AND CEMENT JOBS ☒
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MISU 9-16-84 and drilled out to 7286'. Circulated hole clean and ran tlg. to 10812'. Tested csg to 1000 psi, tested OK. Ran CBL from 10812' - 9000' and 7500' - 7100'. Perfed 10270' - 10280' and 10483' - 10500' w/4SPF using a 3 1/8" gun. RIH with RBP, retrieving tool, pkr, and 2 7/8" tlg. RBP set at 10592', pkr set at 10353'. Swabbed, last 4 hrs recovered 18 BO and 0 BW. Ran base GR/Temp survey and acidized Bone Springs 10483' - 10500' with 2500 gals of 15% NEFE HCl acid. Ran after acid survey and temperature survey. Swabbed and recovered total of 6 BO and 0 BLW last hr. Reset RBP at 10346' and reset pkr. at 10158'. Ran base survey, 2+5 NMOC, H 1-J.R. Barnett, Hon Rm 21.156 1-F.J. Nash, Hon 4.206 1-GCC 1-Mesa 1-Bass

14. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed *May C. Clark* TITLE *Asst. Admin. Analyst* DATE *9-25-84*

ORIGINAL FILED IN OIL CONSERVATION

RECEIVED SEP 27 1984

TITLE

SEP 27 1984

loaded and pressured up backside to 1000 psi. Pumped 1500 gals of 15% NEFE HCl acid w/additives. Tagged acid with RA material. Flushed with 62 bbls 10[#] brine 2% HCl. Ran after acid survey and began swab testing. Currently swab testing.

SEP - 6 1984

217 8 1984