

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-10784

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☒ WELL GAS ☐ WELL OTHER ☐	7. Unit Agreement Name
2. Name of Operator <i>Amoco Production Company</i>	8. Form or Lease Name <i>State HS</i>
3. Address of Operator <i>P.O. Box 68, Hobbs NM 88240</i>	9. Well No. <i>2</i>
4. Location of Well UNIT LETTER <i>L</i> <i>1980</i> FEET FROM THE <i>South</i> LINE AND <i>660</i> FEET FROM THE <i>West</i> LINE, SECTION <i>9</i> TOWNSHIP <i>18-S</i> RANGE <i>34-E</i> N.M.P.M.	10. Field and Pool, or Wildcat <i>West Vacuum Bone Spring</i>
15. Elevation (Show whether DF, RT, GR, etc.) <i>4046.0' CR</i>	12. County <i>Lea</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MISU 10-10-84, drilled out to 8955 and tested csg. 1000 psi for 30 min, OK. Ran cmt bond log 8955'-7800'. Spotted 5 bbl 15% NEFE Acid at 8091'. Perfected 8058'-8066' w/45PF using a 3 1/8" gun. RIH with trip, treating pkr, x-over and seating nipple. Pkr. set at 7805' and seating nipple at 7799'. Swabbed, last hr rec 5 BLW. Ran GR/Temp survey 8250'-7850' and acidized 8058'-8066' with 500 gals 15% NEFE HCL w/add. Ran after acid survey. Swabbed back load and released pkr and P.O.H. RIH with production equipment. Seating nipple set at 8066'. Tested pump to 500 psi for 15 min, O. Presently installing pumping equipment.

J+5 NMACD, W-1-J.R. Barnett, New Rm 2.1.156 O-1-F.J. Nash New Rm 4.206 1-GCC 1-Gulf, Mid

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Gary C. Clark* TITLE *Asst. Admin. Analyst* DATE *10-19-84*

ORIGINAL SIGNED BY JERRY GERTON

APPROVED BY DISTRICT 1 SUPERVISOR

TITLE

DATE

OCT 25 1984

CONDITIONS OF APPROVAL, IF ANY: