

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

API #30-025-28879

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.

7. Unit Agreement Name

N. HOBBS (G/SA) UNIT

8. Farm or Lease Name

SECTION 24

9. Well No.

414

10. Field and Pool, or Whidcat

HOBBS (G/SA)

12. County

LEA

15. Elevation (Show whether DF, RT, GR, etc.)

3671.1' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER RE-PERFORATE, ACIDIZE & SCALE INHIBIT ☒

REMEDIAL WORK ☐  
COMMENCE DRILLING OPS. ☐  
CASING TEST AND CEMENT JOBS ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull production equipment.
2. Spot 500 gals 15% HCl-NEA from 4325' to 3825'.
3. Re-perforate San Andres from 4216' to 4293'.
4. Clean out to 4325'.
5. Acidize and scale inhibit San Andres 4216' - 4293' w/2700 gals 15% HCl-NEA + 105 bbls of Exxon 7647 scale inhibitor.
6. Install production equipment and return well to production.

NSL Order #R-7628.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

*A. J. Fore*  
A. J. FORE

TITLE SUPERVISOR REG. & PERMITTING

DATE MAY 16, 1985

ORIGINAL SIGNED BY JERRY SEXTON

PROVED BY DISTRICT SUPERVISOR

TITLE

DATE

MAY 21 1985

CONDITIONS OF APPROVAL, IF ANY: