## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

		OIL	CONSERV	AHUN.	DIVISI	UN				
D / C D 1000 H.H. NA C 00040				O Pacheco St.			WELL API NO 20,025, 20007			
	Santa Fe	ta Fe, NM 87505			30-025-28887  5. Indicate Type of Lease					
DISTRICT II  811 S. 1st Street, Artesia, N	A 88210						5. Indicate FED	Type of Lease STATI		FEE X
DISTRICT III	4 00210					-		& Gas Lease No.		FEE X
1000 Rio Brazos Rd, Aztec,	NM 87410						J. State Cit.	ce clas Boase 110.		·
	UNDRY NO	TICES AND REP	ORTS ON W	ELLS						
		OPOSALS TO DRILL			ACK TO A		7. Lease Name or Unit Agreement Name			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101 FOR SUCH PROPOSALS.)  1. Type of Well:							NORTH HOBBS (G/SA) UNIT			
1. Type of well: Oil '	Well X	Gas Well	Other							
2. Name of Operator			-				8. Well No	422		
Occidental Permis 3. Address of Operator	ın Ltd.						9 Pool nan	ne or Wildcat	HOBB	S (G/SA)
1017 W. Stanolind	Rd., HOBBS,	NM 88240	505/3	97-8200	,					3 (G/3A)
Unit Letter H	: 2259	Feet From The	NORTH	Line and	600	Feet	From The	EAST	Line	İ
Section	31	Township	18S		Range	38E	>	MPM	LEA	County
		10. Elevation (Sho	w whether DF, R	KB, RT GR, etc	2.)					
		3637 GL		CNI	· D		1 75 .			
		c Appropriate Box ENTION TO:	to indicate N	ature of Not				REPORT	DF:	
PERFORM REMEDIAL W	ORK	PLUG AND ABAN	DON	REMEDIA					G CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING O					NG OPNS	S. [	_	ABANDONI	MENT	
PULL OR ALTER CASING CASING CASING TEST AND CEME										
	San Andres		X	OTHER:						
12. Describe Proposed or Co		ns (Clearly state all ner			nt dates incl	udino est	mated date	of starting any nra	mased work)	
SEE RULE 1103.	пристей Ореганог	is (c. rearry state arr per	imem uetans, an	u give pertiner	n uates, men	auing can	mineu maie (	y situting any pro	розви могк)	
i PULL PRODUCT	•									
	S CANLANIDRE									
2. SQUEEZE UPPEI	COMPANIA	ES PERFS.								
3. RE-PERF.		O PRODUCTION.								
3. RE-PERF.										
3. RE-PERF.										
3. RE-PERF.										
3. RE-PERF.										
3. RE-PERF.										
3. RE-PERF.										
3. RE-PERF.										
3. RÉ-PERF. 4. ACID TREAT AN	D RETURN T	O PRODUCTION.	best of my knowle	edge and helief						
3. RE-PERF. 4. ACID TREAT AN  Thereby certify that the infort	D RETURN T		best of my knowle							> 2 - 0 3
3. RE-PERF. 4. ACID TREAT AN  Thereby certify that the information of the signature of the	D RETURN To	O PRODUCTION.	best of my knowle	edge and belief	PROD E	NGR		DA'		23 - 03
3. RE-PERF. 4. ACID TREAT AN  Thereby certify that the infor	D. NELSON	O PRODUCTION.	best of my knowle			NGR		DA'	505/3	97-8200
3. RE-PERF. 4. ACID TREAT AN  Thereby certify that the information of	D. NELSON	o PRODUCTION.	best of my knowle			NGR		<del></del>	505/3 FE	