

DISTRICT 1

1625 N. French Drive, Hobbs, NM 88240

OIL CONSERVATION DIVISION

310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. <u>28887</u> 10-025- XXXX
5. Indicate Type of Lease FED <input type="checkbox"/> STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NORTH HOBBS (G/SA) UNIT
SECTION <u>31</u>
8. Well No. <u>422</u>
9. Pool name or Wildcat HOBBS (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator <u>OCCIDENTAL PERMIAN LIMITED PARTNERSHIP</u>	
3. Address of Operator <u>1017 W STANOLIND RD.</u>	
4. Well Location Unit Letter <u>H</u> : <u>2250</u> Feet From The <u>NORTH</u> Line and <u>600</u> Feet From The <u>EAST</u> Line Section <u>31</u> Township <u>18-S</u> Range <u>38-E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT GR, etc.) <u>3637' GL.</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input checked="" type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS <input type="checkbox"/> PLUG & ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rig up Pulling Unit (05/03/00)
 Perforate San Andres Zone from 4219' - 4305' (2 JSPE, 180 Degree phased)
 Acidize perts w/4000 gal 15% HCL acid
 RHH W/production equipment. (REDA ESP)
 Rig Down and Clean Location

Rig Up Date: 05/03/00
 Rig Down Date: 05/05/00

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robert N Gilbert TITLE LIFT SPECIALIST DATE 06/01/00
 TYPE OR PRINT NAME R N GILBERT TELEPHONE NO. 505/397-8206

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE 06/01/00

52

2000