

Submit 3 Copies To Appropriate District
Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 87210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.

30-025-28998

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

VB-0393

7. Lease Name or Unit Agreement Name:

Sherry M. State

8. Well No.

1

9. Pool name or Wildcat

Airstrip Bone Springs

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Westbrook Oil Corporation

3. Address of Operator

P O Box 2264, Hobbs NM 88241-2264

4. Well Location

Unit Letter **D** : **330** feet from the **North** line and **660** feet from the **West** line

Section **35** Township **18S** Range **34E** NMPM County **Lea**

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

See attached

Approved as to Plugging of the Well Bore.
Liability under bond is retained until
Surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE **Sec/Treas** DATE **2/12/03**

Type or print name **Barbara Wolfe** Telephone No.

(This space for State use)

APPROVED BY [Signature] TITLE _____ DATE _____

Conditions of approval, if any:

ORIGINAL SIGNED BY
GARY W. WINK
OC FIELD REPRESENTATIVE II/STAFF MANAGER

- 1-7-03 MIU - Pickup 2-3/8" tubing, swabbed perfs 5690' - 5704', swabbed down - no show.
- 1-8-03 Swabbed down - pulled tubing ran CIBP.
- 1-9-03 Set CIBP @ 5600' dumped 35' cement on top of CIBP w/bailer Perf 16 holes from 4656' to 4664' in Queens formation.
- 1-10-03 Ran tubing & Packer to 4600', acidized w/1000 gals, 15% HCL acid, split tubing swabbed acid back.
- 1-11-03 Pull packer replaced split joint & rerun packer to 4600'.
- 1-12-03 S.I.
- 1-13-03 Swabbed well down - acidized w/1000 gals 15% HCL acid, Swabbed well down - no show.
- 1-14-03 Pulled packer & set CIBP @ 4600', 35' cement plug dumped on top of CIBP w/bailer - circulated hole w/mud laden brine.
- 1-15-03 Ran tubing in hole w/packer, pumped 25 sks class C neat cement plug from 4141' to 3841' in 4-1/2" casing. Perf @ 1750' w/2 holes squeezed w/35 sks class C cement leaving 100' plug in 4-1/2. Hold pressure until set. Perf @ 441' w/2 holes squeezed 35 sks of class C cement leaving 100' plug in 4-1/2" casing - Held pressure til set. 10 sk plug set at surface in 4-1/2" casing.
- 1-29-03 Set 4-1/2" Dry Hole Marker. Cleaned location. Ready for inspection.

Plugging procedure - verbal instructions and approval by Johnny Robinson OCD.