

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-29074
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 32
8. Well No. 422
9. Pool name or Wildcat HOBBS (G/SA)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3651.4' DF

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	2. Name of Operator Shell Western E&P Inc.	3. Address of Operator P.O. Box 576 Houston, TX 77001-0576 (WCK 4587)	4. Well Location Unit Letter H : 1385 Feet From The NORTH Line and 110 Feet From The EAST Line Section 32 Township 18S Range 38E NMPM LEA County
--	---	--	--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: OAP & AT; INST LARGER LIFT ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-01 TO 10-08-92:

POH W/PROD EQMT. CO W/BIT & SCRPR TO 4200', POH. SET RBP @ 4000'. SPOT 170 GAL 15% NEFE HCL FROM 3970' TO 3870'. PERF GRAYBURG 3874' - 3969' (2 SPF). ACD PERFS 3940-69' W/1900 GAL 15% NEFE HCL. REL RBP & RESET @ 3937'. ACD GRAYBURG PERFS 3914-34' W/1450 GAL 15% NEFE HCL. REL RBP & RESET @ 4000'. SET PKR @ 3900'. SWB TSTD. REL PKR & RBP. RESET RBP @ 3900', PKR @ 3807'. ATTEMPTD TO ACDZ PERFS 3874-91' W/250 GAL 15% NEFE HCL. PKR FAILED. REL PKR & LATCH ONTO PLUG. FLISH BACKSIDE W/50 BBLS KCL WTR. POH W/PKR & RBP. ACD SA PERFS 4071' - 4222' W/1350 GAL 15% NEFE HCL. RIH W/RBP & PKR. SET RBP @ 3900', PKR @ 3807'. ACD PERFS 3874-91' W/1600 GAL 15% NEFE HCL. REL PKR & RBP, POH. RIH W/LARGER SUBMERSIBLE LIFT EQMT (PMP @ 3839') & RTP.

10-22-92: LOWERED PMP TO 3993' (BELOW GRAYBURG) & SET. RTP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Marcus Winters TITLE TECH. MANAGER - ENVIR. ENG. DATE 11/06/92
TYPE OR PRINT NAME W. F. N. KELLDORF TELEPHONE NO. 713/870-3797

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

NOV 12 '92

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: