

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
SHELL WESTERN E&P INC.

3. Address of Operator
P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)

4. Well Location
Unit Letter H : 2495 Feet From The NORTH Line and 119 Feet From The EAST Line

Section 19 Township 18S Range 38E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3653' GR

7. Lease Name or Unit Agreement Name

N. HOBBS (G/SA) UNIT
SECTION 19

8. Well No.
422

9. Pool name or Wildcat
HOBBS (G/SA)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: WSO, Reperf'd & Acid ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-06 to 3-15-90:

POH w/prod equip. CO to CIBP @ 4185'. Set CIBP @ 4007'. Sqzd GB/SA perfs 4057' - 4182' w/150 SX Cls "C" cmt + 2% CaCl₂ + 1.5% Howco Suds + 0.75% HC-2 + 200 SCF N₂/bbl followed by 50 SX Cls "C" cmt + 2% CaCl₂. Capped CIBP w/2' cmt. DO cmt/CIBP 4005'-07'. Void of cmt to 4063'. DO cmt 4063' - 4185' (CIBP). PT sqz to 500#, held. DO CIBP @ 4185' & pushed to 4330' (PBTD). CO to 4200'. Set CIBP @ 4170'. Perf'd SA 4158'-68' (2 JSPP). Acid perfs 4158'-68' w/300 gals 15% NEFE HCl. Fm wouldn't brk @ 400#. Left well SI overnite w/400# tbg pres. Lost 200# on tbg overnite. Attmpd to brkdn fm w/2500# to no avail. Lost 500# in 10 min w/no fluid movement. Reverse out acid to transport. Reperf'd 4158'-68' (2 JSPP, one misfire). Attmpd to acidz w/300 gals 15% NEFE HCl. Pres to 3000# in 500#

(CONT'D ON REVERSE SIDE)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. Smitherman TITLE REGULATORY SUPV. DATE 4-30-90

TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)

ORIGINAL RETURN TO OIL CONSERVATION
DISTRICT OFFICE

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAY 2 1990

increments, no pres brk. Reversed out acid. Pmpd 300 gals 15% NEFE HCl. Pres to 2000# in 500# increments w/no fluid movement. SI overnite w/1000# tbg pres. Next AM, 0# on tbg, 500# on csg. Ld tbg w/5.3 bbls fresh wtr, fm took fluid. Overdispl acid by 6 bbls. Inst prod equip & ret'd to prod.