

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-29291
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other WIW <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator SAGA PETROLEUM LLC		6. State Oil & Gas Lease No. Federal Unit Agreement
3. Address of Operator 415 W WALL, SUITE 1900 MIDLAND, TX 79701		7. Lease Name or Unit Agreement Name CENTRAL CORBIN QUEEN UNIT Agreement NMNM84603X
4. Well Location Unit Letter M : 330 feet from the S line and 330 feet from the W line Section 3 Township 18S Range 33E NMPM County LEA		8. Well No. 601
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat Corbin Queen, Central

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐
OTHER: Press test after HIT repair ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.

12-5-02 HIT-Bleed dwn well, NDWH, NU BOP, release pkr, POOH, looking for HIT, no hole found, will bull plug test tbg Fri AM. DC:\$970 12-6 RIH w/BP tbg test to 2000 psi very 10 stds -HIT #120 - POOH. PU 2-3/8"x5-1/2"AD-1 pkr, & RIH. ND BOP NUWH. circ pkr fluid, NDWH, & set pkr, NU WH, test csg & prk 500 psi, good test. OCD on location.
2-3/8"x5-1/2" AD-1 pkr
132 jts - 4101' 2-3/8" duoline tbg

12-6-02 Press up to 580 psi - hel for 30 mins - good test - Witness by EL Gonzales of OCD- Chart attached

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Husband TITLE Production Analyst DATE 12/10/2002

Type or print name Bonnie Husband

Telephone No. (915)684-4293

(This space for State use)

APPROVED BY

ORIGINAL SIGNED BY

GARY W. TWINE

DATE 12-10-02

Conditions of approval, if any:

OCD FIELD REPRESENTATIVE II/STAFF MANAGER

