Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103	
<u>District I</u> 1625 N. French Dr., Hobbs, NM 87240	Energy. Minerals and Natural Resources		Revised March 25, 1999 WELL API NO.	
District II			30-025-29296	
District III 2040 South Pacheco		5. Indicate Type of Lease		
District IV Santa Fe, NM 87410 Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.		
2040 South Pacheco, Santa Fe, NM 87505			Federal Unit Agreement	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name CENTRAL CORBIN QUEEN UNIT	
1. Typc of Well: Oil Well □ Gas Well □ OtherWIW			Agreement NMNM84603X	
2. Name of Operator SAGA PETROLEUM LLC			8. Well No. 401	
3. Address of Operator 415 W WALL, SUITE 1900 MIDLAND, TX 79701			9. Pool name or Wildcat Corbin Queen, Central	
4. Well Location			Coroni Queen, C	entrai
Unit Letter C: 660 feet from the North line and 1980 feet from the West line				
Section 9	Township18S Ra	ange 33E	NMPM	CountyLEA
	10. Elevation (Show whether DR, 3965' GL	RKB, RT, GR, etc.)		·
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INT.	ENTION TO: PLUG AND ABANDON	SUB REMEDIAL WOR	SEQUENT RE	PORT OF: ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS.	PLUG AND
	MULTIPLE COMPLETION	CASING TEST AN	ND	ABANDONMENT
OTHER:		OTHER:Workover	r, return to inj - pre	ss test X
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.				
3-3-03 Release pkr, TOOH w/tbg & pkr, bullplug, test tbg to 3000 psi every row, pinhole jt #36. remainder tbg test good POOH w/tbg.				
131 (2-3/8") PC tbg EOP 4078', AD-1 pkr 3-4-03 PU 2-3/8" x 5-1/2" AD-1 pkr, RIH w/tbg & pkr, land tbg, ND BOP, NUWH, circ pkr fluid - NDWH - set pkr - NUWH - test				
csg to 500 psi for 30-mins - test good	l witness by J Robinson Hobbs O	CD, put well on inj.	Chart attached	•
				hencos oco
				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE BONNE SUS	trandTITLEJ	Production Analyst	1	DATE 03/05/2003
Type or print nameBonnie Husband			Tele	phone No. (915)684-4293
(This space for State use)				
APPROVED BY	Colonal Signeles Cary W. Wink	ź.		DMAR_1 1 2003
Conditions of approval, if any:	OARY W. WINK OA FIELD REFRESHM	ATIVE HISTAFF AL	NAGER	LUUJ

5 こ ら

