•	RECOMMENDED WORK PROCEDURE	Sun-5036-3-C				
	WELL NAME	FIELD NAME	······································	COUNTY	STATE	
	Mescalero Ridge 'B' Fed. No.		scarpe	Lea	New Me	vice
		UPPERMOST PLUG		RETAINER		<u>•x1co</u>
	KB: 4008 GL: 3996	PBTD: 9102		None		
	CASING $5\frac{1}{2}$, 15.5 & 17#, K-55	CS: 9221	PACKER DEPTH (TOP) & TYPE		(2) (3)	
	SIZE, WEIGHT, GRADE, ETC. TUBING 2-7/8",6.5#,J-55	DEPTH SET TS: 8781	TOP OF CEMEN BEHIND PROD (None T CALCULATED	, <u>Log</u> 3300' (1	
	P.U. Size: MK640-305-168	DEPTH SET	PERFS Rone Spring			
		PROCEDU		9 Set I 8736-8	776, 2 JSPF	
1.	MI RU PU. POH w/rods & pump. NU BOP. Rise TAC. Load hole w/2% KCL fresh wtr.					RIGTIM
	Drop SV to SN. Pressure test tbg to ±5000 psi (if hole is not full, downgrade test pressure accordingly). Fish SV. POH w/2-7/8", 6.5#, J-55 production tbg standing back.					10
2.	RIH w/5½", 17# sqz pkr & SN on 2-7/8" prod tbg to ±8500. Set pkr. Howco sqz perfs 8736-8776 w/100 sks Class 'C' cmt w/.4% Halad 9 & 10 lb/sk HDPL-370 (expansive additive). Sqz to max 4000 psi surface press. Rev excess cmt & pull 3 stands. Re set pkr, trap sqz press & SI for 4 hours. Test sqz to 2000 psi. Rlse pkr and POH.					12
3.	RIH w/4-3/4" RB & 6 3½" DC's on 2-7/8" prod tbg. DO cmt sqz. Test sqz to 2000 psi. POH.					10
4.	Gearhart perf Bone Spring Set I 8736-8752, 2 JSPF, total 33 holes using 4" OD, 23 GC, .48 EH csg gun via Schlum GR/CN-LD log dated 9-17-85. (Cost quot e for job \$1065).					2
5.	RIH w/5½" RDG pkr (Sun owned stock) & SN on 2-7/8" tbg to ± 8650 . Set pkr. Swab test perfs natural for evaluation of fluid entry. POH.					10
6.	RIH w/5½" B.JTitan 'PFT' on 2-7/8" tbg to ±8736 (top perf). Break circ w/NE treated 2% KCL fresh wtr. Round trip tool thru perfs while circ at ±2 BPM. Raise tool back to top perf.					4
7.	Circ 500 gals 20% NEFE HCL w/additives* to 'PFT'. SI backside. Pump 250 gals 20% NEFE HCL while moving tool dn thru perfs. Repeat while pulling tool back to top perf. Use treated 2% KCL fresh wtr to displace acid into perfs. SI 15 Min.					1
8.	POH w/tbg & PFT.					3
9.	RIH w/5½", 17# RDG pkr (Sun owned stock) & SN on 2-7/8" prod tbg to ± 8625 '. Set pkr. Swab back L&AW. Eval FE rate & content to confirm no channeling or communication has been established. Open bypass and load hole. B.J. Titan spot 1000 gals 20% NEFE HCL w/additives* to ± 500 ' from pkr. Close bypass. Trap 500 psi CP. Disp acid into perfs 8736-52 at $\frac{1}{2}$ BPM at max surf press of 2000 psi. Disp acid using NE treated 2% KCL fresh wtr. Record ISIP, 5, 10 & 15 Min SIP					10
10.	Flow/swab back L&AW. Eval FE rate & content to confirm no channeling or communication has been established. Rlse pkr & POH.					10
11.	RIH w/2-7/8" production tbg as before, SN ± 8784 . RIH w/1.5" pump on 86 taper rod string as before. RR.					8
12.	Put well in production test Monitor fluid level daily.	at 1.5 X 168 X	10 (100% pur	np capacity of	375 BPD).	
_					Total Hours	80

