

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-50920
2. NAME OF OPERATOR Mewbourne Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 7698, Tyler, Texas 75711		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 1980' FEL		8. FARM OR LEASE NAME Federal "I"
14. PERMIT NO. API #30-025-29345		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3876.4' GL		10. FIELD AND POOL, OR WILDCAT Reeves-Penn
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 14-18S-35E
		12. COUNTY OR PARISH Lea
		13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input checked="" type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Set RBP at 11,047 and dumped 2 sac of sand on top.
1/25/86 - RU Welex and perforated the Strawn formation from 10,907-916', overall 9', 18 holes. PU Otis permalack packer and TIH with tubing. Set packer at 10,786' with 14 points compression.
1/28/86 - RU Western and acidized Strawn perfs with 2000 gallons of 15% HCL acid + 25 ball sealers. FBP 5000#, maximum 5800# at 3.2 BPM, minimum 5000# at 3.7 BPM, average 5200# at 3.5 BPM, ISDP 4400#, 5 minutes 3800#, 10 minutes 2800#, 15 minutes 1900#. RD Western.

ACCEPTED FOR RECORD

SWC
FEB 3 1986

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *Raymond Simpson* TITLE Exploration Secretary

DATE 1/28/86

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side