Ferm 3160-5 (November 1983) (Formerly 9-331)

## UNITED STATES SUBMIT IN TRIPLICA ... (Other Instructions on re-

5.	LEASE	DESI	GNATION	AND BI	C R I

DATE 11/04/85

DATE .

Budget Burcau No. 1004-0.3

Form approved.

k t	М-	ζ	n	а	0	Λ	
N	M-	フ	U	7	۷	U	

BUREAU OF LAND MANAGEMENT	O. FOR A A.A.A.	NM-50920		
SUNDRY NOTICES AND REPORTS C	N WELLS	6 IF INDIAN, ALLOTTEE OR TRIBE NAME		
1.		7. UNIT AGREEMENT NAME		
WELL X WELL OTHER		8. FARM OR LEASE NAME		
2. NAME OF OPERATOR Mewbowrne Oil Company		Federal "I"		
3. ADDRESS OF OPERATOR		9. WELL NO.		
P. O. Box 7698, Tyler, Texas 75711	1			
<ol> <li>Location of Well (Report location clearly and in accordance with any See also space 17 below.)</li> <li>At surface</li> </ol>	Reeves-Penn			
1980' FSL & 1980' FEL	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA			
	and the same of th	14-18S-35E 12. COUNTY OR PARISH; 13. STATE		
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, API #30-025-29356 3876.4' GL	Lea N.M.			
16. Check Appropriate Box To Indicate N	ature of Notice, Report, or	Other Data		
NOTICE OF INTENTION TO:	SUBSE	QUENT REPORT OF:		
TEST WATER SHUT-OFF  FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL LOTher)  PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON® CHANGE PLANS	Completion or Recou	REFAIRING WELL  ALTERING CASING  ABANDONMENT*  ts of multiple completion on Well  apletion Report and Log form.)		
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent proposed work. If well is directionally drilled, give subsurface locat nent to this work.)	ions and measured and true vert	icut deptus for an markers and zones perti-		
10/15/85 - Rigged up Welex. Perforated Devoni PU Otis permalatch packer and ran in hole wit	lan from 12,207-216' th 389 jts 2-7/8" tu	, 9' and 18 holes. RD Welex. bing. Set packer at 12,148.80'		
10/16/85 - Started swabbing. Swabbed 125 bbl swab below 4000'.	's of water with show	w of gas each run. Could not		
10/17/85 - Shut in overnight. Made 2 swab run Released packer. TOOH with tubing. RU Welex top of plug. RD Welex.	is, all formation wa and set CIBP at 12,	ter with no show of oil. 170'. Dumped 10' cement on		
10/18/85 - PU Otis Permalatch packerand tubin packer at 10,972.26'. RU swab. Swabbed down to 11,100-123', 23' and 24 holes. No show after blow of gas.	to SN. RU Welex and	perforated Morrow formation		
10/19/85 - Swabbed well down to SN. RU Hallit with 35 ball sealers.	ourton and acidized (	with 2500 gals 25% NE-FE acid		
10/29/85 - NO production - Preparing to re-ac	ridize.			
$10/30/85$ - RU Western and acidized Morrow per 25 tons of $CO_2$ .	forations with 12,0	00 gals 15% gelled acid plus		

ADVECTOR BY FOR SICORD CONDITIONS OF APPROVAL, IF ANY: NOV 12 1985

(This space for Federal or State office use)

\*See Instructions on Reverse Side

RECEIVED

NOV 1 3 1985

OCC SHOPES CANCER