

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL. (Other instructions on reverse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. 226-26884-A
2. NAME OF OPERATOR OXY USA Inc.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 50250, Midland, TX 79710	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' ENL & 660' FEEL	8. FARM OR LEASE NAME Federal AG
	9. WELL NO. 1
	10. FIELD AND POOL, OR WILDCAT Central Corbin Queen
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 3-T18S-R33E
14. PERMIT NO. 30-025-29483	12. COUNTY OR PARISH Lea
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3948' GR	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

This well was plugged and abandoned in the following manner:

1. MIRU pulling unit and pull rods, ND WH, NV BOP and POOH w/tubing.
2. RU w/wireline and set a 8-5/8" CIBP @ 4180'. Dumped 6 sacks of cement on top of BP from 4180' to 4158', plugging off the Queen Perfs @ 4218'-4248'.
3. POOH w/tbg. to 1609'. Pump 30 sacks cement from 1609'-1499'. Displaced plug w/mud laden fluid.
4. POOH to 495'. Pump 30 sacks cement from 495'-385', 1/2 in and 1/2 out of 13-3/8" csg. shoe @ 450'. Displaced plug w/mud laden fluid. POOH to 52'. Pump 14 sacks cement from 52' to surface.
5. Cut off WH and casing below the GL and install a 4" dry hole marker to designate a plugged and abandoned location.

18. I hereby certify that the foregoing is true and correct

SIGNED FA Veterans TITLE Dist. Oper. Mgr. - Prod. DATE 10-27-88

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 11-21-88
CONDITIONS OF APPROVAL, IF ANY:

U.S. Dept. of the Interior
Bureau of Land Management

*See Instructions on Reverse Side

RECEIVED

NOV 23 1988

OCB
HOBBS OFFICE