

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-29489
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-3229
7. Lease Name or Unit Agreement Name ABO "13" State
8. Well No. 1
9. Pool name or Wildcat Reeves (Bone Spring)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Mitchell Energy Corporation	
3. Address of Operator Box 4000, The Woodlands, TX 77387	
4. Well Location Unit Letter D : 660 Feet From The North Line and 330 Feet From The West Line Section 13 Township 18S Range 35E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3881' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/12/93 MIRU PU. POOH w/277 jts 2 7/8" tbg.
10/13/93 RIH w/CIBP & set @ 8500'. RIH w/270 jts 2 7/8" tbg & tag plug.
10/14/93 Displ hole w/9.5# mud. Spot 25 sx cmt on top of CIBP. POOH w/180 jts tbg.
10/18/93 Shot 5 1/2" csg @ 5100' - could not pull. Shot @ 5028' - could not pull. Shot csg @ 4848'. Could not pull. Shot @ 3020' - could not pull.
10/19-20/93 Shot csg @ 2987'. POOH w/75 jts 5 1/2" csg. RIH w/tbg to 5012'. Loaded hole w/mud. Spotted 50 sx cmt plug from 5020' to 4538'. PU to 3037' & spot 40 sx plug. POOH w/50 jts tbg.
10/21/93 RIH w/tbg & tag plug @ 2927'. Circ hole w/salt gel. POOH w/tbg to 1870'. Spotted 50 sx cmt. POOH w/tbg to 100' & spotted 50 sx plug @ surf. Dug out cellar.
10/22/93 Cut off WH & weld P&A marker. Cut anchors & cleaned location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James Blount TITLE Engineer DATE 11/2/93
TYPE OR PRINT NAME James Blount TELEPHONE NO. (915) 682-5396

(This space for State Use)

APPROVED BY Johnny Robinson TITLE State Engineer DATE 11/2/93
CONDITIONS OF APPROVAL, IF ANY: