·		
NO. OF COPIES RECEIVED]	Form C-103
DISTRIBUTION		Form C-103 Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE		Tuestine 1-1-02
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
		E-1582
DO NOT USE THIS FO	SUNDRY NOTICES AND REPORTS ON WELLS RM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS WELL WELL	OTHER-	7. Unit Adreement Name
2. Name of Operator		8. Farm or Lease Name
Tamarack Petroleum Co., Inc.		Arco "28" State
3. Address of Operator 1405 One First City Conton Millian I TRY 20201		9. Well No.
	st City Center, Midland, TX 79701	2
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER B	1650 FEET FROM THE East LINE AND 330 FEET FR	Reeves (Queen)
North	20 10.0 25.7	
THEL	INE, SECTION 28 TOWNSHIP 18-S RANGE 35-E	~ (
mmmm	15. Elevation (Show whether DF, RT, GR, etc.)	
	3913.8 GR	12. County Lea
16.	Charle American D. T. I. I. N. Carle D.	
NOTE	Check Appropriate Box To Indicate Nature of Notice, Report or C	
NOTE	SUBSEQUE	NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	Г
TEMPORARILY ABANDON	PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	ALTERING CASING
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB X	PLUG AND ABANDONMENT
L	OTHER_	Г
OTHER		
	mpleted Operations (Clearly state all pertinent details, and give pertinent dates, includi	ng estimated date of starting any propos
17. Describe Proposed or Co work) SEE RULE 1103.		ng estimated date of starting any propos
17. Describe Proposed or Co work) SEE RULE 1103. 1. Spud 12-1	.4-85. Drilled 11" hole to 475'.	ng estimated date of starting any propos
17. Describe Proposed or Cowork) SEE RULE 1103. 1. Spud 12-1 2. Ran 12 jt	.4-85. Drilled 11" hole to 475'. cs. 8 5/8" 24# K-55 casing. Set at 475' on 12/15/85	
17. Describe Proposed or Cowork) SEE RULE 1103. 1. Spud 12-1 2. Ran 12 jt 3. Cemented	4-85. Drilled 11" hole to 475'. s. 8 5/8" 24# K-55 casing. Set at 475' on 12/15/85 to surface with 300 sks Class "C" 2% CaCl ₂ & 1/4# Ce	
17. Describe Proposed or Cowork) SEE RULE 1103. 1. Spud 12-1 2. Ran 12 jt 3. Cemented Circulate	4-85. Drilled 11" hole to 475'. s. 8 5/8" 24# K-55 casing. Set at 475' on 12/15/85 to surface with 300 sks Class "C" 2% CaCl ₂ & 1/4# Ce	llocele per sack.
17. Describe Proposed or Cowork) SEE RULE 1103. 1. Spud 12-1 2. Ran 12 jt 3. Cemented Circulate 4. Nippled U	.4-85. Drilled 11" hole to 475'. cs. 8 5/8" 24# K-55 casing. Set at 475' on 12/15/85 to surface with 300 sks Class "C" 2% CaCl ₂ & 1/4# Ce cd 80 sks cement to surface. up 11" 5000 PSI Shaffer IWS Double Ram and 11" 5000 P	llocele per sack.
17. Describe Proposed or Cowork) SEE RULE 1103. 1. Spud 12-1 2. Ran 12 jt 3. Cemented Circulate 4. Nippled u & tested t	A-85. Drilled 11" hole to 475'. s. 8 5/8" 24# K-55 casing. Set at 475' on 12/15/85 to surface with 300 sks Class "C" 2% CaCl ₂ & 1/4# Ce ed 80 sks cement to surface. p 11" 5000 PSI Shaffer LWS Double Ram and 11" 5000 P co 2000 PSI.	llocele per sack.
17. Describe Proposed or Cowork) SEE RULE 1103. 1. Spud 12-1 2. Ran 12 jt 3. Cemented Circulate 4. Nippled u & tested t 5. Drilled 7	A-85. Drilled 11" hole to 475'. S. 8 5/8" 24# K-55 casing. Set at 475' on 12/15/85 to surface with 300 sks Class "C" 2% CaCl ₂ & 1/4# Ce ed 80 sks cement to surface. Ap 11" 5000 PSI Shaffer IWS Double Ram and 11" 5000 P ED 2000 PSI. 7/8" hole from 475 to 4427.	llocele per sack.
17. Describe Proposed or Cowork) SEE RULE 1103. 1. Spud 12-1 2. Ran 12 jt 3. Cemented Circulate 4. Nippled u & tested t 5. Drilled 7 6. Cored 7 2	A-85. Drilled 11" hole to 475'. s. 8 5/8" 24# K-55 casing. Set at 475' on 12/15/85 to surface with 300 sks Class "C" 2% CaCl ₂ & 1/4# Ce d 80 sks cement to surface. p 11" 5000 PSI Shaffer LWS Double Ram and 11" 5000 P to 2000 PSI. 7/8" hole from 475 to 4427. 67/32" hole from 4427 to 4486'.	llocele per sack.
17. Describe Proposed or Cowork) SEE RULE 1103. 1. Spud 12-1 2. Ran 12 jt 3. Cemented Circulate 4. Nippled to & tested t 5. Drilled 7 6. Cored 7 2 7. Drilled 7	4-85. Drilled 11" hole to 475'. 28. 8 5/8" 24# K-55 casing. Set at 475' on 12/15/85 to surface with 300 sks Class "C" 2% CaCl ₂ & 1/4# Cet 80 sks cement to surface. 29 11" 5000 PSI Shaffer IWS Double Ram and 11" 5000 Pto 2000 PSI. 27/8" hole from 475 to 4427. 27/32" hole from 4427 to 4486'. 27/8" hole from 4486 to 4560.	llocele per sack.
17. Describe Proposed or Cowork) SEE RULE 1103. 1. Spud 12-1 2. Ran 12 jt 3. Cemented Circulate 4. Nippled u & tested t 5. Drilled 7 6. Cored 7 2 7. Drilled 7 8. Ran open	4-85. Drilled 11" hole to 475'. s. 8 5/8" 24# K-55 casing. Set at 475' on 12/15/85 to surface with 300 sks Class "C" 2% CaCl ₂ & 1/4# Ce d 80 sks cement to surface. p 11" 5000 PSI Shaffer LWS Double Ram and 11" 5000 P co 2000 PSI. 7/8" hole from 475 to 4427. 17/32" hole from 4427 to 4486'. 17/8" hole from 4486 to 4560. hole logs on 12/23/85	llocele per sack.
17. Describe Proposed or Cowork) SEE RULE 1103. 1. Spud 12-1 2. Ran 12 jt 3. Cemented Circulate 4. Nippled u & tested t 5. Drilled 7 6. Cored 7 2 7. Drilled 7 8. Ran open 9. Ran 109 j	A-85. Drilled 11" hole to 475'. S. 8 5/8" 24# K-55 casing. Set at 475' on 12/15/85 to surface with 300 sks Class "C" 2% CaCl ₂ & 1/4# Ce ed 80 sks cement to surface. April 10 5000 PSI Shaffer IWS Double Ram and 11" 5000 Pto 2000 PSI. To 7/8" hole from 475 to 4427. To 7/8" hole from 4427 to 4486'. To 7/8" hole from 4486 to 4560. The top 12/23/85 to 41/2" 10.5# K-55 casing to 4559 on 12/24/85.	llocele per sack. SI Shaffer Sperical BOPI
17. Describe Proposed or Cowork) SEE RULE 1103. 1. Spud 12-1 2. Ran 12 jt 3. Cemented Circulate 4. Nippled u & tested t 5. Drilled 7 6. Cored 7 2 7. Drilled 7 8. Ran open 9. Ran 109 j 10. Cement wi	4-85. Drilled 11" hole to 475'. 28. 8 5/8" 24# K-55 casing. Set at 475' on 12/15/85 to surface with 300 sks Class "C" 2% CaCl ₂ & 1/4# Cet 80 sks cement to surface. 29 11" 5000 PSI Shaffer IWS Double Ram and 11" 5000 Pto 2000 PSI. 27/8" hole from 475 to 4427. 27/32" hole from 4427 to 4486'. 27/8" hole from 4486 to 4560. 38 hole logs on 12/23/85 39 ts 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 30 th 1050 sks Pacesetter Lite Class H 3# salt & 1/4# C	llocele per sack. SI Shaffer Sperical BOPM ellocele per sack
17. Describe Proposed or Cowork) SEE RULE 1103. 1. Spud 12-1 2. Ran 12 jt 3. Cemented Circulate 4. Nippled to & tested t 5. Drilled 7 6. Cored 7 2 7. Drilled 7 8. Ran open 9. Ran 109 j 10. Cement witailed in	4-85. Drilled 11" hole to 475'. 25. 8 5/8" 24# K-55 casing. Set at 475' on 12/15/85 to surface with 300 sks Class "C" 2% CaCl ₂ & 1/4# Cet 80 sks cement to surface. 25. 2000 PSI Shaffer IWS Double Ram and 11" 5000 Pto 2000 PSI. 26. 7/8" hole from 475 to 4427. 27/32" hole from 4427 to 4486'. 27/8" hole from 4486 to 4560. 28. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 29. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 30. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 31. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 32. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 33. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 34. 5 1/4# Cet 9/8 CF-14. Circulated	llocele per sack. SI Shaffer Sperical BOPF ellocele per sack
17. Describe Proposed or Cowork) SEE RULE 1103. 1. Spud 12-1 2. Ran 12 jt 3. Cemented Circulate 4. Nippled to & tested t 5. Drilled 7 6. Cored 7 2 7. Drilled 7 8. Ran open 9. Ran 109 j 10. Cement witailed in	4-85. Drilled 11" hole to 475'. 28. 8 5/8" 24# K-55 casing. Set at 475' on 12/15/85 to surface with 300 sks Class "C" 2% CaCl ₂ & 1/4# Cet 80 sks cement to surface. 29 11" 5000 PSI Shaffer IWS Double Ram and 11" 5000 Pto 2000 PSI. 27/8" hole from 475 to 4427. 27/32" hole from 4427 to 4486'. 27/8" hole from 4486 to 4560. 38 hole logs on 12/23/85 39 ts 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 30 th 1050 sks Pacesetter Lite Class H 3# salt & 1/4# C	llocele per sack. SI Shaffer Sperical BOPF
17. Describe Proposed or Cowork) SEE RULE 1103. 1. Spud 12-1 2. Ran 12 jt 3. Cemented Circulate 4. Nippled to & tested t 5. Drilled 7 6. Cored 7 2 7. Drilled 7 8. Ran open 9. Ran 109 j 10. Cement witailed in	4-85. Drilled 11" hole to 475'. 25. 8 5/8" 24# K-55 casing. Set at 475' on 12/15/85 to surface with 300 sks Class "C" 2% CaCl ₂ & 1/4# Cet 80 sks cement to surface. 25. 2000 PSI Shaffer IWS Double Ram and 11" 5000 Pto 2000 PSI. 26. 7/8" hole from 475 to 4427. 27/32" hole from 4427 to 4486'. 27/8" hole from 4486 to 4560. 28. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 29. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 30. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 31. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 32. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 33. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 34. 5 1/4# Cet 9/8 CF-14. Circulated	llocele per sack. SI Shaffer Sperical BOPM ellocele per sack
17. Describe Proposed or Cowork) SEE RULE 1103. 1. Spud 12-1 2. Ran 12 jt 3. Cemented Circulate 4. Nippled to & tested t 5. Drilled 7 6. Cored 7 2 7. Drilled 7 8. Ran open 9. Ran 109 j 10. Cement witailed in	4-85. Drilled 11" hole to 475'. 25. 8 5/8" 24# K-55 casing. Set at 475' on 12/15/85 to surface with 300 sks Class "C" 2% CaCl ₂ & 1/4# Cet 80 sks cement to surface. 25. 2000 PSI Shaffer IWS Double Ram and 11" 5000 Pto 2000 PSI. 26. 7/8" hole from 475 to 4427. 27/32" hole from 4427 to 4486'. 27/8" hole from 4486 to 4560. 28. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 29. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 30. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 31. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 32. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 33. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 34. 5 1/4# Cet 9/8 CF-14. Circulated	llocele per sack. SI Shaffer Sperical BOPM ellocele per sack
17. Describe Proposed or Cowork) SEE RULE 1103. 1. Spud 12-1 2. Ran 12 jt 3. Cemented Circulate 4. Nippled u & tested t 5. Drilled 7 6. Cored 7 2 7. Drilled 7 8. Ran open 9. Ran 109 j 10. Cement witailed in	4-85. Drilled 11" hole to 475'. 25. 8 5/8" 24# K-55 casing. Set at 475' on 12/15/85 to surface with 300 sks Class "C" 2% CaCl ₂ & 1/4# Cet 80 sks cement to surface. 25. 2000 PSI Shaffer IWS Double Ram and 11" 5000 Pto 2000 PSI. 26. 7/8" hole from 475 to 4427. 27/32" hole from 4427 to 4486'. 27/8" hole from 4486 to 4560. 28. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 29. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 30. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 31. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 32. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 33. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 34. 5 1/4# Cet 9/8 CF-14. Circulated	llocele per sack. SI Shaffer Sperical BOPM ellocele per sack
17. Describe Proposed or Cowork) SEE RULE 1103. 1. Spud 12-1 2. Ran 12 jt 3. Cemented Circulate 4. Nippled u & tested t 5. Drilled 7 6. Cored 7 2 7. Drilled 7 8. Ran open 9. Ran 109 j 10. Cement witailed in	4-85. Drilled 11" hole to 475'. 25. 8 5/8" 24# K-55 casing. Set at 475' on 12/15/85 to surface with 300 sks Class "C" 2% CaCl ₂ & 1/4# Cet 80 sks cement to surface. 25. 2000 PSI Shaffer IWS Double Ram and 11" 5000 Pto 2000 PSI. 26. 7/8" hole from 475 to 4427. 27/32" hole from 4427 to 4486'. 27/8" hole from 4486 to 4560. 28. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 29. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 30. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 31. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 32. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 33. 4 1/2" 10.5# K-55 casing to 4559 on 12/24/85. 34. 5 1/4# Cet 9/8 CF-14. Circulated	llocele per sack. SI Shaffer Sperical BOPF

District Engineer

DATE 1-3-86

DATE JAN7 - 1986

ORIGINAL SIGNED BY JERRY BEXTON

DISTRICT I SUPERVISOR

