		양. 11	O. BOX 1950 USBS DEW MEXICO 88240	
orm 3160-5 June 1990)			FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5 Lease Designation and Serial No.	
SUN Do not use this form fo Use "A	0 NMNM26884 6. If Indian, Allottee or Tribe Name OIT.			
	7. If Unit or CA, Agreement Designation			
1. Type of Well  Cas Well Other  2. Name of Operator			8. Well Name and No. 008599 Federal AB #4	
OXY USA Inc. 16696 3 Address and Telephone No.			9. API Well No. 30-025-29531	
P.O. Box 50250         Midland, TX         79710         915-685-5717           4 Location of Well (Footage, Sec., T., R., M., or Survey Description)         990 FSL         660 FEL         SESE         Sec. 11         T18S         R33E			,	
CHECK APP	ROPRIATE BOX(s) TO	O INDICATE NATURE OF NOTICE, RE	PORT, OR OTHER DATA	
TYPE OF SUBM		TYPE OF ACTION		
X Notice of Intent	ori	Abandonment Recompletion Plugging Back Casing Repair	Change of Pians Change of Pians New Construction Non-Routine Fracturing Water Shut-Off	
Final Abandon		Altering Casing Altering Casing Other <u>Perf Add'l Interva</u> Acidize & Frac hent details, and give pertinent dates, including estimated date of	Conversion to Injection Conversion to Injection Dispose Water Note Report results of multiple completion on Well Completion or Recompletion Report and Log form 1	
	_	ths for all markers and zones pertinent to this work.)*	2 1	
	SEI	E OTHER SIDE	FES 17 TES	
14. I hereby certify that the foregoing	Bg is true and correct			
14. I hereby certify that the foregoing Signed	David Stew	art <sub>Title</sub> Regulatory Analyst	Date2/16/95	

\*See instruction on Reverse Side

- 1.) MIRU pulling unit. TOOH w/ rods and pump. ND WH, NU BOP. TOOH w/ tbg and TAC.
- 2.) RU wireline and run gauge ring to 8650'. TIH w/ CIBP on wireline and set CIBP @ ±8620'.
- 3.) Perforate 2nd Bone Springs Sand formation (8477'- 8568') w/ premium. shots 1 JSPF at the following depths: 8477', 8478', 8489', 8495', 8498', 8509', 8522', 8543', 8547' - 8568'. Total of 30 shots. Depth. reference log Schlumberger Compensated Neutron - Litho Density Log dated January 1, 1986.
- 4.) TIH w/ pkr on 2-7/8" tubing and set pkr @ ±8350'. RU Acid Co. and acidize Bone Springs Sand perfs (8477' - 8568') w/ 4000 gals 15% Ne Fe HCl utilizing 60 RCNBS. Flush w/ 2% KCl wtr. Swab back load.
- 5.) TOOH w/ pkr and tbg.
- 6.) RU Frac Co., Frac Bone Springs Sand perfs (8477' 8568') down 5 1/2" csg w/ 113,000 gals xlinked gelled 2% KCl wtr (35# system), 190,000# 16/30 Ottawa sand, and 60,000# 16/30 Resin Coated sand at 30 BPM as follows:
  - a.) Pump 45,000 gals pad.
  - b.) Pump 8,000 gals with 1 ppg 16/30 Ottawa sand.
  - c.) Pump 10,000 gals with 2 ppg 16/30 Ottawa sand.
  - d.) Pump 12,000 gals with 3 ppg 16/30 Ottawa sand.
  - e.) Pump 14,000 gals with 4 ppg 16/30 Ottawa sand.
  - f.) Pump 14,000 gals with 5 ppg 16/30 Ottawa sand.
  - g.) Pump 10,000 gals with 6 ppg 16/30 Resin Coated sand.
  - h.) Flush w/ gelled 2% KCl wtr (10# system).
  - h.) Open well to pit and initiate forced closure by flowing back well at 0.5 BPM for 1 hour. SION.
- 7.) Open well and flow back or swab load.
- 8.) TIH w/ 2-7/8" tbg for production. ND BOP, NU WH. TIH w/ rods and pmp. RDMO pulling unit. Put well on production.

1833 (1871) 1977 - 1977 1977 - 1977 1977 - 1977