

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPI
(Other instructions
verse 10)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-61604

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

FEB 19 1987

UNIT AGREEMENT NAME

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

MURPHY OPERATING CORPORATION

3. ADDRESS OF OPERATOR

P. O. Box 2648, Roswell, New Mexico 88202-2648

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

455' FNL & 2310' FEL, Unit Ltr. B, Sec. 20, T-18S, R-33E

8. FARM OR LEASE NAME

South Corbin Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Corbin Bone Spring, South

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 20, T-18S, R-33E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DT, RT, CR, etc.)

3842' G.R., 3860' K.B.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) perforate & acidize

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

X

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

2-09-87 RU PU. TOH w/rods. TOH w/35 stands of tbgs. SDFN.

2-10-87 RU loggers & TIH w/perf guns & perf. as follows: 7374', 7369', 7366.5', 7362', 7359', 7354', 7350', 7348', 7345', 7340', 7338.5' & 7337.5' (total 12 holes shot). Total 24 holes in zone. RD loggers. TIH w/pkr. to 7172' KB set pkr. Complete acid job as follows:

24 bbls MSR 123 acid

250 gals. Xylene

Dropped 50 balls & well did ball off. Avg. rate @ 3 BPM, Max. rate @ 3 BPM, Max. press. @ 4950# psi. Final press. @ 3310# psi & avg. press. @ 3000# psi. ISIP @ 2060# psi, 5 min. @ 650#, 10 min. @ 510#, 15 min. @ 200# psi. 91 bbls. total left to rec. Blowed well dn. RU swabb & started swabbing, rec. 48 bbls.

2-11-87 SITP, small blow, not enough to register on gauge. RU swabb line & started swabbing (43 bbls. left to rec.). Rel. pkr. & TIH to 7330'. Rec. 73 bbls. over load. Changed elev. & ran rods in hole. Hung well on w/good pump action.

I hereby certify that the foregoing is true and correct

SIGNED

Lois N. Brown

TITLE Production Clerk

DATE Feb. 18, 1987

ACCEPTED FOR RECORD

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

FEB 20 1987

JUL

CARLSBAD, NEW MEXICO

*See Instructions on Reverse Side