

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-101
Supersedes Old
C-102 and C-103
Effective 1-1-65
30-025-29547

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - FORM C-101 FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Spectrum 7 Exploration Company	8. Farm or Lease Name Sun 28
3. Address of Operator 1610 North J, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>1880</u> FEET FROM THE <u>West</u> LINE, SECTION <u>28</u> TOWNSHIP <u>18S</u> RANGE <u>34E</u> N.M.P.M.	10. Field and Pool, or Wildcat Undesignated
11. Elevation (Show whether DF, RT, GR, etc.) 4028.2' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/15/86 Move in & rig up service unit. Pulled rods & pump. Tripped tubing and went in hole open ended. Bottom of tubing @ 4500'. Spotted 25 sx plug.

4/16/86 Went in hole with wireline and tagged top of plug @ 4108'. Cut and pulled 4 1/2" casing @ 2788'. Tripped in hole and spotted 45 sx plug @ 2827'.

4/17/86 Went down hole and tagged top of plug @ 2723'. Spotted 45 sx plug @ 1444'. Tripped out of hole. Waited 4 hours. Went in hole with wireline and tagged top of plug @ 1418'. Nippled down heads and cut off 8 5/8" casing. Set 10 sx plug @ surface. Welded on plate and dry hole marker. Plugging complete @ 3:45 p.m. on 4/17/86.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Neal A Taylor</u>	TITLE <u>Petroleum Consultant</u>	DATE <u>4/24/86</u>
APPROVED BY <u>R. A. Hille</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>MAY 13 1987</u>

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JUN 21 1986
O.C.D.
HIGHER OFFICE

1986 JUN 21