

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
B-1520

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Mobil Producing TX & NM Inc.	8. Farm or Lease Name Bridges State
3. Address of Operator 9 Greenway Plaza, Suite 2700, Houston, TX 77046	9. Well No. 506
4. Location of Well UNIT LETTER <u>N</u> <u>830</u> FEET FROM THE <u>South</u> LINE AND <u>2175</u> FEET FROM THE <u>West</u> LINE, SECTION <u>13</u> TOWNSHIP <u>17-S</u> RANGE <u>34-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Vacuum - Strawn
15. Elevation (Show whether DF, RT, GR, etc.) KB - 4032.5	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Convert from Flowing to Pumping</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- 7-23-86 MIRU Diamond WS, POH
- 7-24-86 Mill out pkr @ 10880, did not rec pkr, tag milled over pkr @ 8476 & fell free to 10990, quit going-unable to work pkr dn, POH
- 7-25/27-86 RIH w/cutrite shoe, tag mdl pkr @ 10996, mill & push dn hole to 11318, circ hole clean, POH.
- 7-28-86 RIH w/SN-11274,TAC-10846 on 368 jts 2-7/8 tbg, tbg string 35' off btm.
- 7-29-86 RIH w/2½ x 1½ x 34 pump, press tbg 5000#-OK, RDMO, turn to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Nancy Lewis TITLE Authorized Agent DATE 8-4-86

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR TITLE _____ DATE AUG 7 1986

CONDITIONS OF APPROVAL, IF ANY: