

4. RIH with submersible pump, SN, and 2 7/8" tubing. Set pump at previously set depth. ND BOP. NU well head. RDMO pulling unit.
5. Connect to surface facilities and begin pumping. Report rates to the Midland office.

7777 7777 7777 7777

RECEIVED
JUN 28 1993
10:00 AM
10:00 AM