CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico
En , Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease STATE S	DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088				WELL API NO.			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS POWN FOR PROPOSALS TO DRILL OR TO DEEPEN ON PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS. 1. Type of Wait. CWIL. [2] 2. Name of Operator Mobil Producing TX & MM Inc.* 1. Address of Operator Mobil Producing TX & MM Inc.* 1. Address of Operator Mobil Producing TX & MM Inc.* 1. Address of Operator Mobil Producing TX & MM Inc.* 1. Address of Operator Mobil Producing TX & MM Inc.* 1. Type of Wait. CWIL LIST Tomaking 17-S Reage 34-E NMTM LEA Conservation 13 Tomaking 17-S Reage 34-E NMTM LEA Conservation 13 Tomaking 17-S Reage 34-E NMTM LEA Conservation 13 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF Internation TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK SALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONING COMMENCE AND ABANDONING				5. Indicate Type of Lease				
COD NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DEFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) Type of Well:	DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			:			FEE	
Topic a Mail: Wall Wall Other Wall Wall Other	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"				-			
Mobil Producing TX & NM Inc.* 3. Address of Openers "Mobil Exploration & Producing U.S. Inc. as Agent for Mobil Producing TX & NM Inc.; P.O. Box \$33, Midland , TX 79702 4. Well Lossion Usit Later G. ; 2135 Fost From The NORTH Line and 1905 Feet From The EAST Line Section 13 Township 17-S Range 34-E NMTM LEA County NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CASING TEST AND CEMENT JOB 10. Describe Proposed or Completed Operations (Clearly state all partitions details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1-15-90 MIRU, POON W/RODS+PUMP. NU BOP. POON W/360 JTS 2 3/8 TBG. 1-16-90 RIH W/CIBG TO 11, 100° & CAP W/35° CMT. RIH W/SIT & SERAPER TO 4 100°. 1-18-90 PERF MIDDLE PENN 100° & CAP W/35° CMT. RIH W/SIT & SERAPER TO 4 100°. 1-19-90 THE W/TBG TO 8600° - RESE YOR & TEST 3009 (LEAK OFF). 1-20-90 XCHANGE PIR (MODEL R) RESE TYPE R 10385-TEST type To 1000 (LEAK OFF). 1-20-90 RIH W/DID & FOODS RIGHT REST 1000 (LEAK OFF). 1-20-90 RIH W/DID & FOODS RIGHT REST PIRR & TEST 3009 (LEAK OFF). 1-20-90 RIH W/DID & FOODS RIGHT REST PIRR & TEST 3009 (LEAK OFF). 1-20-90 RIH W/DID & FOODS RIGHT REST PIRR & TEST 3009 (LEAK OFF). 1-20-90 RIH W/DID & FOODS RIGHT REST PIRR & TEST 3009 (LEAK OFF). 1-20-90 RIH W/DID & FOODS RIGHT REST PIRR & TEST 3009 (LEAK OFF). 1-20-90 RIH W/DID & FOODS RIGHT REST PIRR & TEST 3009 (LEAK OFF). 1-20-90 RIH W/DID & FOODS RIGHT REST PIRR & TEST 3009 (LEAK OFF). 1-20-90 RIH W/DID & FOODS RIGHT REST PIRR & TEST 3009 (LEAK OFF). 1-20-90 RIH W/DID & FOODS RIGHT REST PIRR & TEST 3009 (LEAK OFF). 1-20-90 RIH W/DID & FOODS RIGHT REST PIRR & TEST 3009 (LEAK OFF). 1-20-90 RIH W/DID & FOODS RIGHT REST PIRR & TEST 3009 (LEAK OFF). 1-20-90 RIH W/DID & FOO		OTHER			BRIDGES STA	ile		
Section 13 Township 17-S Range 34-E NMPM LEA County 10. Elevation (Show whather DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data, including estimated data of starting any proposed worth) SEE RULE 1103. 1-15-90 MIRU, POOH W/ROOS+PUMP. NU BOP. POOH W/350 JTS 2 3/8 TBG. 1-16-90 RIH W/CIBP TO 11, 100' & CAP W/35' CMT. RIH W/ANOTHER CIBP TO 10,500. RIH W/CIBP TO 11, 100' & CAP W/35' CMT. RIH W/ANOTHER CIBP TO 10,500. RIH W/CIBP TO 11, 100' & CAP W/35' CMT. RIH W/ANOTHER CIBP TO 10,500. RIH W/CIBP TO 11, 100' & ROW Z/JSPF (94 HOLES) RIH W/MODEL R PKR & SN TO 8600'. 1-18-90 PERF MIDDLE PENN 10450-10498 RIH W/BIT & SCRAPER TO 4100'. 1-18-90 PERF MIDDLE PENN 10450-10498 W/ZJSPF (94 HOLES) RIH W/MODEL R PKR & SN TO 8600'. 1-19-90 TH W/TBG-SET PKR & TEST 3009 (JCK. ACDZ W/98BLS TO 4700 POOH W/TBG TO 8600'-RESET PKR & TEST 3009 (JCK. ACDZ W/98BLS TO 4700 POOH W/TBG TO 8600'-RESET PKR & TEST 3009 (JCK. ACDZ W/98BLS TO 4700 POOH W/TBG TO 8600'-RESET PKR & TEST 3009 (JCK. ACDZ W/98BLS TO 4700 POOH W/TBG TO 8600'-RESET PKR & TEST 3009 (JCK. ACDZ W/98BLS TO 4700 POOH W/TBG TO 8600'-RESET PKR & TEST 3009 (JCK. ACDZ W/98BLS TO 4700 POOH W/TBG TO 8600'-RESET PKR & TEST 3009 (JCK. ACDZ W/98BLS TO 4700 POOH W/TBG TO 8600'-RESET PKR & TEST 3009 (JCK. ACDZ W/98BLS TO 4700 POOH W/TBG TO 8600'-RESET PKR & TEST 3009 (JCK. ACDZ W/98BLS TO 4700 POOH W/TBG TO 8600'-RESET PKR & TEST 3009 (JCK. ACDZ W/98BLS TO 4700 POOH W/TBG TO 8600'-RESET PKR & TEST 3009 (JCK. ACDZ W/98BLS TO 4700 POOH W/TBG TO 8600'-RESET PKR & TEST 3009 (JCK. ACDZ W/98BLS TO 4700 POOH W/TBG TO 8600'-R	Mobil Producing TX & NM II 3. Address of Operator *Mobil Exploi Producing TX & NM Inc.; P.0 4. Well Location	ration & Producing U.S. In D. Box 633, Midland ,TX	nc., a 79702	s Agent for Mobil 2	513 9. Pool name or 1			
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all perinent datalle, and give pertinent data, including estimated data of starting any proposed wort). SEE RULE 1103. 1-15-90 MIRU, POOH W/RODS+PUMP. NU BOP. POOH W/360 JTS 2 3/8 TBG. 1-16-90 RIH W/CIBP TO 11, 100' & EQ 104/6-10498. RIH W/SIBPER TO 4100'. 1-18-90 PERF MIDDLE PENN 10450-10496 W/ZJSPF (94 HOLES) RIH W/MODEL R PKR & SN TO 8600'. 1-19-90 TIH W/TBG-SET PKR & TEST 3009 (LEAK OFF). 1-20-90 XCHANGE PKR (MODEL R) SET PKR & TEST 3009 (LEAK OFF). 1-20-90 XCHANGE PKR (MODEL R) SET PKR & TEST 3009 (LEAK OFF). 1-22-90 RIH W/DTID & rods. Rig dn & rel to prod. 1 benefy certify that the information above is the and complete to the best of my boowledge and bestef. 1 SKONATURES D. W. PARKS, JR. 1 TELEPHONE NO. 688-2548 (This space for State Use) ORIGINAL SIGNED.	Unit Letter G : 2135	Feet From The NORTH		Line and 1905	Feet From	n The EAST	Line	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: OTHER		10. Elevation (Show wh	ether Di	F, RKB, RT, GR, etc.)		T Data	County	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENT TO THER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including entimated date of starting any proposed work) SEE RULE 1103. 1-15-90 MIRU, POOH W/RODS+PUMP. NU BOP, POOH W/360 JTS 2 3/8 TBG. 1-16-90 RIH W/CIBP TO 11, 100' & CAP W/35' CMT. RIH W/ANOTHER CIBP TO 10,600. RIH W/CIBP TO 11,100' & CAP W/35' CMT. RIH W/ANOTHER CIBP TO 10,600. RIH W/CIBP TO 10450-10498. RIH W/BIT & SCRAPER TO 4100'. 1-18-90 PERF MIDDLE PENN 10450-10498 M/2JSPF (94 HOLES) RIH W/MODEL R PKR & SN TO 8600'. 1-18-90 PERF MIDDLE PENN 10450-10498 W/2JSPF (94 HOLES) RIH W/MODEL R PKR & SN TO 8600'. 1-19-90 TH W/TBG TO 8600'-RESET PKR & TEST 300# (LEAK OFF). 1-20-90 XCHANGE PKR (MODEL R) SET 910365-TEST tbg to 7000#/no leaks. 1-21-90 Acdz 10450-10494 W/4000 gals 15% DINEFFE + 125 RONES 3 stages. Flush w/40 bbls FW. 1-22-90 RIH W/pmp & rods. Rig dn & rel to prod. 1 beneby certify that the information above is true and complete to the best of my tronvictige and belief. Regulatory Technician PATE 02-01-90 TYPS OR FRINT NAME D. W. PARKS, JR. TELEPHONE NO. 688-2548 (This space for State Use) ORIGINAL SCREEN AND A STAR AND A								
PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHE	PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK	X	ALTERING CASING	a [
OTHER: OTHER: OTHER: OTHER:	TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING	OPNS.	PLUG AND ABANE	ONMENT	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1-15-90 MIRU, POOH W/RODS+PUMP. NU BOP.POOH W/360 JTS 2 3/8 TBG. 1-16-90 RIH W/CIBP TO 11, 100° & CAP W/35° CMT. RIH W/ANOTHER CIBP TO 10,600. RIH W/CSG GUN & PERF 10476-10498. RIH W/BIT & SCRAPER TO 4100°. 1-18-90 PERF MIDDLE PENN 10450-10496 W/2JSPF (94 HOLES) RIH W/MODEL R PKR & SN TO 8600°. 1-19-90 TIH W/TBG-SET PKR @10365. PRESS CSG TO 300#/CK. ACDZ W/9BBLS TO 4700 POOH W/TBG TO 8600°-RESET PKR & TEST 300# (LEAK OFF). 1-20-90 XCHANGE PKR (MODEL R) SET @10365-Test tbg to 7000#/no leaks. 1-21-90 Acdz 10450-10494 w/4000 gals 15% DINEFE + 125 RCNBS 3 stages. Flush w/40 bbls FW. 1-22-90 RIH w/pmp & rods. Rig dn & rel to prod. TITLE Regulatory Technician DATE 02-01-90 TYPE OR FRINT NAME D. W. PARKS, JR. TELEPHONE NO. 688-2548	PULL OR ALTER CASING			CASING TEST AND CEMENT JOB				
Work) SEE RULE 1103. 1-15-90 MIRU, POOH W/RODS+PUMP. NU BOP. POOH W/360 JTS 2 3/8 TBG. 1-16-90 RIH W/CIBP TO 11, 100' & CAP W/35' CMT. RIH W/ANOTHER CIBP TO 10,600. RIH W/CSG GUN & PERF 10476-10498. RIH W/BIT & SCRAPER TO 4100'. 1-18-90 PERF MIDDLE PENN 10450-10496 W/2JSPF (94 HOLES) RIH W/MODEL R PKR & SN TO 8600'. 1-19-90 THH W/TBG-SET PKR @10365. PRESS CSG TO 300#/CK. ACDZ W/9BBLS TO 4700 POOH W/TBG TO 8600'-RESET PKR & TEST 300# (LEAK OFF). 1-20-90 XCHANGE PKR (MODEL R) SET @10365-Test tbg to 7000#/no leaks. 1-21-90 Acdz 10450-10494 w/4000 gals 15% DINEFE + 125 RCNBS 3 stages. Flush w/40 bbls FW. 1-22-90 RIH w/pmp & rods. Rig dn & rel to prod. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIONATURE TITLE Regulatory Technician DATE 02-01-90 TYPEOR PRINT NAME D. W. PARKS, JR. TELEPHONE NO. 688-2548 (This space for State Use)	OTHER:	[OTHER:	-	·	[
1-16-90 RIH W/CIBP TO 11,100' & CAP W/35' CMT. RIH W/ANOTHER CIBP TO 10,600. RIH W/CSG GUN & PERF 10476-10498. RIH W/BIT & SCRAPER TO 4100'. 1-18-90 PERF MIDDLE PENN 10450-10496 W/2JSPF (94 HOLES) RIH W/MODEL R PKR & SN TO 8600'. 1-19-90 TIH W/TBG-SET PKR @10365. PRESS CSG TO 300#/OK. ACDZ W/9BBLS TO 4700 POOH W/TBG TO 8600'-RESET PKR & TEST 300# (LEAK OFF). 1-20-90 XCHANGE PKR (MODEL R) SET @10365-Test tbg to 7000#/no leaks. 1-21-90 Acdz 10450-10494 w/4000 gals 15% DINEFE + 125 RCNBS 3 stages. Flush w/40 bbls FW. 1-22-90 RIH w/pmp & rods. Rig dn & rel to prod. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Regulatory Technician DATE 02-01-90 TYPE OR PERMITNAME D. W. PARKS, JR. TELEPHONE NO. 688-2548	12. Describe Proposed or Completed Opera work) SEE RULE 1103.	tions (Clearly state all pertinent deta	ils, and	give pertinent dates, includ	ling estimated date of	of starting any propose	d	
SIGNATURE OF FRONT NAME D. W. PARKS, JR. Regulatory Technician DATE 02-01-90 TYPE OR PRINT NAME D. W. PARKS, JR. TELEPHONE NO. 688-2548 (This space for State Use)	1-16-90 RIH W/CIBP TO 11,1 RIH W/CSG GUN & F 1-18-90 PERF MIDDLE PENN 1-19-90 TIH W/TBG-SET PKI POOH W/TBG TO 86 1-20-90 XCHANGE PKR (MODI 1-21-90 Acdz 10450-1049 Flush w/40 bbls	100' & CAP W/35' CMT. FPERF 10476-10498. RIM V 10450-10496 W/2JSPF & R @10365. PRESS CSG TO 500'-RESET PKR & TEST 3 EL R) SET @10365-Test 94 w/4000 gals 15% D S FW.	RIH W. W/BIT (94 H 300# 300# tbg	/ANOTHER CIBP TO & SCRAPER TO 410 OLES) RIH W/MODE 6/OK. ACDZ W/9BB (LEAK OFF). to 7000#/no le E + 125 RCNBS	00'. ELRPKR&SN LSTO4700 aks.	TO 8600'.		
ORIGINAL SECRED DY LESSON OF A LET	SIGNATURE OW Parks.	7	-	- 1. m	echnician			
作(で)わったや 1 フェースというけん 5	· ·					Party See	e Tourist State	
	DISTENTY E L		_ TITLE				5 1490 	