

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG-3801	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- Notification to Plug & Abandon		7. Unit Agreement Name	
2. Name of Operator M. Brad Bennett		8. Farm or Lease Name Buffalo "32" State	
3. Address of Operator P.O. Box 2062 Midland, TX 79702		9. Well No. 1	
4. Location of Well UNIT LETTER <u>M</u> , <u>330</u> FEET FROM THE <u>south</u> LINE AND <u>330</u> FEET FROM THE <u>west</u> LINE, SECTION <u>32</u> TOWNSHIP <u>18S</u> RANGE <u>33E</u> NMPM.		10. Field and Pool, or Wildcat Buffalo (Yates)	
15. Elevation (Show whether DF, RT, GR, etc.) 3715.3' GR		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

Propose to plug and abandon the subject well as follows:

MIRU; POOH w/Pkr; RIH w/CIBP & set @ 3462'; Cap w/35' cmt (5 sx); Displ hole w/plugging mud (25# gel/bbl); Spot 100' cmt (25 sx) fr 1552' to 1452'; Cut 5-1/2" csg @ 410' & pull; Spot 35 sx fr 50' inside 8-5/8" csg shoe to 50' below base of 8-5/8" csg (Note - 5-1/2" csg stub @ 410'); Spot 10 sx cmt plug on surface & erect abandonment marker; Fill pits & level location & clear junk; Shall notify NMOCC prior to rigging up.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>M. Brad Bennett</u>	TITLE <u>Individual</u>	DATE <u>10/16/86</u>
ORIGINAL SIGNED BY JERRY SEXTON		
APPROVED BY <u>DISTRICT 1 SUPERVISOR</u>	TITLE <u></u>	DATE <u>OCT 20 1986</u>

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
OCT 17 1986  
O.C.C.  
HOBBS OFFICE