orm 3160-5 iune 1990)

UNT STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

1.	ļ.,	tu se	to Dis	;	a tilli maran
₽.	\sim	503	1911		

Hc 3S, NEW MINIOPERSONAL Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lesse Designation and Serial No.

NMNM84603X - NMLCo29489B
6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

SUBM	7. If Unit or CA, Agreement Designation Central Corbin Queen Unit	
	Injection	8. Well Name and No. 209
OXY USA Inc.	16696	9. API Well No. 30-025-29777
P.O. Box 50250 Midland,		10. Field and Pool, or Exploratory Area 013
ation of Well (Footage, Sec., T., R., M., or Surve		Corbin Queen, Central 11. County or Parish, State Lea NM
CHECK APPROPRIATE BO	DX(s) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Subsequent Report Final Abandonment Notice	Abendonment Recompletion Plugging Back Casing Repair Altering Casing Other Test Tbg, Clean out	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection E Dispose Water
	Acidize. sate all pertinent details, and give pertinent dates, including estimated date of starts	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
TD - 4450'	PBTD - 4398' Perfs - 4152-4166'	
MIRU PU 2/5/96, NDWH, NUBC 4398'. RIH & set pkr @ 40 2430#. Swab 0-BO & 77-BW 2-3/8" tbg, test tbg to 30 pkr fluss set pkr @ 4057 notified, did not witness	PBTD - 4398' Perfs - 4152-4166' OP, POOH w/ pkr & tbg. RIH & Tag @ 405 O48', acidize w/ 3000gal 15% NeFe HCl a in 5hrs, swab dry. POOH w/ pkr, RIH w O00#, replace 1 seal, tbg tested OK. N '. Pressure test csg to 300# for 30 mi . RDPU 2/8/96, put well back on inject	cid, MaxP-4150#, SITP- / Guiberson G-6 pkr & DBOP, NUWH, Circ hole w/ n, held OK. NMOCD
MIRU PU 2/5/96, NDWH, NUBO 4398'. RIH & set pkr @ 40 2430#. Swab 0-BO & 77-BW 2-3/8" tbg, test tbg to 30 pkr fluse, set pkr @ 4057	OP, POOH w/ pkr & tbg. RIH & Tag @ 405 048', acidize w/ 3000gal 15% NeFe HCl a in 5hrs, swab dry. POOH w/ pkr, RIH w 000#, replace 1 seal, tbg tested OK. N '. Pressure test csg to 300# for 30 mi	cid, MaxP-4150#, SITP- / Guiberson G-6 pkr & DBOP, NUWH, Circ hole w/ n, held OK. NMOCD
MIRU PU 2/5/96, NDWH, NUBO 4398'. RIH & set pkr @ 40 2430#. Swab 0-B0 & 77-BW 2-3/8" tbg, test tbg to 30 pkr flute, set pkr @ 4057 moetified, didenot witness Thereby certify that the foregoing a true and correct Thereby certify that the foregoing a true and correct Thereby certify that the foregoing a true and correct Thereby certify that the foregoing a true and correct	OP, POOH w/ pkr & tbg. RIH & Tag @ 405 048', acidize w/ 3000gal 15% NeFe HCl a in 5hrs, swab dry. POOH w/ pkr, RIH w 000#, replace 1 seal, tbg tested OK. N '. Pressure test csg to 300# for 30 mi . RDPU 2/8/96, put well back on inject HOBBS INSPECTION OFFICE ACCEPTED FOR RECORD DATE 3-1/-96 SIGNATURE UPB	cid, MaxP-4150#, SITP- / Guiberson G-6 pkr & DBOP, NUWH, Circ hole w/ n, held OK. NMOCD ion. ACCAR THE 22 THE 33
MIRU PU 2/5/96, NDWH, NUBC 4398'. RIH & set pkr @ 40 2430#. Swab 0-BO & 77-BW 2-3/8" tbg, test tbg to 30 pkr fluss, set pkr @ 4057 notified, did not witness	OP, POOH w/ pkr & tbg. RIH & Tag @ 405 048', acidize w/ 3000gal 15% NeFe HCl a in 5hrs, swab dry. POOH w/ pkr, RIH w 000#, replace 1 seal, tbg tested OK. N '. Pressure test csg to 300# for 30 mi . RDPU 2/8/96, put well back on inject HOBBS INSPECTION OFFICE ACCEPTED FOR RECORD DATE 3-1/-96 SIGNATURE UPB	cid, MaxP-4150#, SITP- / Guiberson G-6 pkr & DBOP, NUWH, Circ hole w/ n, held OK. NMOCD ion.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent sor representations as to any manner within its jurisdiction.

