

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-29864
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-476

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Moonrise ALU State
2. Name of Operator YATES PETROLEUM CORPORATION	8. Well No. 1
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	9. Pool name or Wildcat Albuquerque Junction Area Undesignated Delaware
4. Well Location Unit Letter <u>M</u> : <u>330</u> Feet From The <u>South</u> Line and <u>330</u> Feet From The <u>West</u> Line Section <u>27</u> Township <u>18S</u> Range <u>36E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3795.5' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-19-94 - NOTE: Notified Bonnie with OCD that operations would be commencing. Moved in and rigged up pulling unit. Nippled down wellhead. POOH with rods and tubing. Nippled up BOP. RIH with 2-7/8" tubing for workstring. Shut down for night.

7-20-94 - POOH with 2-7/8" tubing. Picked up 5-1/2" tubing. RIH w/2-7/8" tubing and CIBP. Set CIBP at 4450'. Mixed and pumped 20 sacks Class "C" 2% CaCl2 from 4450-3550' in 5-1/2" casing. POOH with 2-7/8" tubing to 4330'. Reverse circulate clean. Spotted 30 bbls plug mud from 4330-3000' in 5-1/2" casing. POOH with 2-7/8" tubing to 3860'. Mixed and spotted 25 sacks Class "C" 2% CaCl2 from 3860-3760' in 5-1/2" casing. POOH with 2-7/8" tubing. Laid down stinger. Nippled down BOP and wellhead. Welded 5-1/2" pull nipple. Picked up on casing and pulled slips. Took casing stretch - estimate free point at 3200'. Rigged up wireline. Ran and cut casing at 3100' with 4-3/4" jet cutter. Rigged down wireline. Picked up and worked casing. Rigged up pump and pressured to 1000#, no loss. Worked casing. Took another stretch - estimate free point at 3200'. Rigged up wireline. Picked up and ran 4-3/4" jet cutter to 3000'. Shut down for night.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 7-26-94
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE 18