

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-29864
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-476
7. Lease Name or Unit Agreement Name Moonrise ALU State
8. Well No. 1
9. Pool name or Wildcat Arkansas Junction Butch Undesignated Delaware Gas

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	4. Well Location Unit Letter M : 330 Feet From The South Line and 330 Feet From The West Line Section 27 Township 18S Range 36E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3795.5' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Approval was obtained by Mike Allen, Completion Foreman with Yates Petroleum Corporation, from Gary Wink with the Oil Conservation Division in Hobbs, to plug and abandon well as follows: NOTE: Approval obtained on April 7, 1994.

1. Move in and rig up pulling unit. Pull production tubing and packer.
2. Set a 5-1/2" CIBP at 4450' and cap with 35' of cement.
3. Spot a 25 sack Class "C" 2% CaCl₂ plug from 3860-3760' (across 8-5/8" shoe).
4. Circulate hole from 3700' with 9# brine with 25#/barrel salt gel.
5. Cut and pull 5-1/2" casing at 3100'±. Cement bond log showed top of cement at 3200'.
6. Spot a 25 sack Class "C" 2% CaCl₂ plug from 3150-3050' (across stub).
7. Spot a 10 sack Class "C" 2% CaCl₂ plug at surface.
8. Install regulation abandonment marker.

NOTE: NOTIFY OCD (393-6161) 24 HOURS PRIOR TO COMMENCING PLUGGING OPERATIONS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE April 7, 1994
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

APPROVED BY _____ TITLE DISTRICT I SUPERVISOR DATE APR 11 1994

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR