

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG 1910	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A		7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation		8. Farm or Lease Name Airpath AEM State
3. Address of Operator 105 South 4th St., Artesia, NM 88210		9. Well No. 1
4. Location of Well UNIT LETTER P 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 8 TOWNSHIP 18S RANGE 36E NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3838' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 13004'. Plugged well as follows:

- Plug #1 12844-12744' w/40 sacks Class "H" with .3% WR-2 retorter.
PD 9:05 AM 4-27-87.
- Plug #2 11525-11425' w/120 sacks Class "H" with .3% WR-2 retorter.
PD 10:32 AM 4-27-87.
- Plug #3 10200-10100' w/40 sacks Class "H" with .3% WR-2 retorter.
PD 11:54 AM 4-27-87.
- Plug #4 6960-6860' w/40 sacks Class "H" neat.
PD 2:18 PM 4-27-87.
- Plug #5 5250-5150' w/50 sacks Class "H" neat.
PD 4:40 PM 4-27-87.
- Plug #6 3850-3750' w/45 sacks Class "H" neat.
PD 5:38 PM 4-27-87.
- Plug #7 2100-2000' w/35 sacks Class "H" neat.
PD 6:38 PM 4-27-87.
- Plug #8 100'-surface w/30 sacks Class "H" neat.
PD 7:40 PM 4-27-87.

Clean location and install dry hole marker.

Verbal permission given by Jerry Sexton, NMOCD, Hobbs for plugging 4-25-87.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Production Supervisor DATE 4-28-87

APPROVED BY [Signature] OIL & GAS INSPECTOR DATE MAY 3 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
APR 30 1987
OCD
SOABs OFFICE