

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-025-29908

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

TONTO 15 STATE

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

8. Well No.  
# 2

2. Name of Operator  
SOUTHLAND ROYALTY COMPANY

9. Pool name or Wildcat  
AIRSTRIP BONE SPRING, N.

3. Address of Operator  
P.O. Box 51810, Midland, TX 79710-1810

4. Well Location  
Unit Letter H : 550' Feet From The EAST Line and 1880' Feet From The NORTH Line

Section 15 Township 18S Range 34E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐


SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: REPERF AND STIMULATE ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/25/93: MIRU. 10/26/93: POH W/PMP AND RODS. RLSE TAC. INSTALL BOP. PU TBG. RH AND TAG AT 9780'. RU PMP TRK AND PMP 110 GLS OF TRETOLITE PAO-100 AND 110 GLS OF SUPER A SOL WLC 0603 W/56 BBLS OF LEASE CRUDE OIL. POOH W/TBG. 10/27/93: RU WIRELINE. RIH W/4" GUNS AND PERFORATE 9672' TO 9694'. RIH AND SHOT 9528' - 9535'. GUN BECAME STUCK. PULLED OUT OF CABLE HEAD. W/O FISHING TOOL. PU OVERSHOT. BMPER SUB AND RIH ON TBG TO 9511. POOH W/TBG AND OVERSHOT LAY DOWN PERFORATING GUN. RU WIRELINE AND RIH A/4" GUN AND PERFORATE 970'-9750'. RD WIRELINE. 10/28/93: TIH W/PCL TOOL TO 9750'. RU ACID ENGR AND ACDZ PERFS 9750'-9740' W/500 GLS, 9672'-9694' W/ 100 GLSD, 9528'-9535' W/400 GLS OF PENTOL 250 15% NEFE HCL. POOH W/SONIC HAMMER TOOL AND TBG. RIH W/TBG. SET TAC W/14 PTS TENSION. ND BOP. NU WH. SWAB. 10/29/93: CONTINUE IN HOLE W/RODS. SPACE OUT AND HANG ON. RU PMP TRUCK AND LOAD AND TEST. HAD GOOD PP ACTION. TURN WELL OVER TO PRODUCTION. H

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE 

TITLE PRODUCTION ASSISTANT

DATE 11/4/93

TYPE OR PRINT NAME DONNA WILLIAMS

TELEPHONE NO. 915-688-6943

(This space for State Use)

Orig. Signed by  
Paul Kautz  
Geologist

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_

DATE NOV 15 1993

CONDITIONS OF APPROVAL, IF ANY: