

TONTO 15 STATE # 2
CONT.

LAY DOWN SONIC HAMMER.

9. RERUN PRODUCTION TBGING, PMP AND RODS AND RETURN WELL TO PRODUCTION. (IF TUBING ANCHOR CATCHER IS ACTUALLY AT +/-9530' AS INDICATED ON PULLING REPORTS, IT SHOULD BE REPOSITIONED TO +/-9460' WHEN RUNNING BACK IN HOLE)
10. PLACE WELL ON TEST