

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-29949
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2229
7. Lease Name or Unit Agreement Name: Philmex
8. Well No. 20
9. Pool name or Wildcat Maljamar / Gravituro San Andres

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street Odessa, TX 79762	
4. Well Location Unit Letter D : 660 feet from the North line and 660 feet from the West line Section 36 Township 17-S Range 33-E NMPM County Lea	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4127' KB / 4118' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

03/20/02 MIRU BASIC ENERGY SERVICES P & A PACKAGE #2282. OBJECTIVE: PLUG AND ABANDON "PHILMEX #20, LOCATED: 660' FNL & 660' FWL, SEC 36, T-17-S, R-33-E, LEA COUNTY, NEW MEXICO. NOTIFIED NMCD SYLVIA DICKIE W/INTENT TO COMMENCE PLUG AND ABANDON OPERATIONS. DIG TESS CONFIRMATION #2002101207. ND WH, NU CLASS 1 BOP. FU WS & CCCR, GTH TO 3220'. ATTEMPT TO CCCR, TUBING PLUGGED. POOH, CCCR PLUGGED W/SCALE. SECURE WELL SDON.

*** CONTINUED ON BACK ***

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *L. M. Sanders* TITLE Supervisor, Reg./Pro. DATE 04/01/02
Type or print name L. M. Sanders Telephone No. 915/368-1488

(This space for State use)

APPROVED BY *Johnny Robinson* TITLE COMPLIANCE OFFICER DATE NOV - 1 2002
Conditions of approval, if any:

GW

Continued:

PHILMEX #20

03/22/02 GIH W/ BIT & SCRAPER TO 3220'. POOH. GIH W/ CICR TO 3220'. EST PUMP RATE = 0 PSI @ 3 BBL/MIN. SQUEEZE PLUG #1 (100 SX THROUGH CICR @ 3220'. 0 PSI @ 3 BBL/MIN. UNSTING FROM CICR). PUMP PLUG #2 (60 SX, INTERVAL 3220'-2614', DISPLACE W/ 11 BBL MLF. POOH - LD WS TO 2000', CIRC 40 BBL MLF. POOH - LD WS TO 1650'. PUMP PLUG #3 (30 SX, INTERVAL 1650'-1347', DISPLACE W/4.5 BBL MLF). POOH. WOC. GIH W/WS. TAG PLUG #3 @ 1333'. POOH - LD WS TO 750', STAND BACK 750' TBG. RIG DOWN FLOOR AND PREP FOR CASING PULL. SECURE WELL & SDON.

03/24/02 TRAVEL TO LOCATION. ND BOPE, DIG OUT CELLAR. PREP TO PULL 5-1/2" CASING. PULL ON 5-1/2" CASING. NO STRETCH. GIH W/ JET CUTTER. CUT 5-1/2" CASING @ 450'. LAY DOWN 12 JTS 5-1/2" CASING. RIG UP FLOOR AND TOOLS. GIH W/ WS TO 500'. PUMP PLUG #4 (45 SX, INTERVAL 350'-500', DISPLACE W/ 3 BBL MLF). POOH W/WS. WOC GIH TAG PLUG #4 @ 304'. LD WS TO 100'. PUMP PLUG #5 (25 SX, INTERVAL 100'-SURFACE). LD WS. RDMO. PERFORM RECLAMTION WORK. CAP AND INSTALL DRY HOLE MARKER. P & A OPERATIONS COMPLETE. DROP FROM REPORT.

MATERIAL TRANSFER

#799493 -
#799494 -

5-1/2" CASING
WELLHEAD ACCESS