

U. S. DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
RECEIVED  
NOV 2 8 18 AM '87

CATE  
OR RE

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. NAME OF OPERATOR Harvey E. Yates Company	3. ADDRESS OF OPERATOR P.O. Box 1933, Roswell, New Mexico 88201	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 330' FNL & 330' FEL	5. LEASE DESIGNATION AND SERIAL NO. NM-21172	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	7. UNIT AGREEMENT NAME	8. FARM OR LEASE NAME Sheldon 15 Federal	9. WELL NO. #1	10. FIELD AND POOL, OR WILDCAT Mescalero Escarpe Bone	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 15, T-18S, R33E	12. COUNTY OR PARISH Lea	13. STATE NM
14. PERMIT NO. 30-025-30031	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3971.2 GL											

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF  
FRACTURE TREAT  
SHOOT OR ACIDIZE  
REPAIR WELL  
(Other)

PULL OR ALTER CASING  
MULTIPLE COMPLETION  
ABANDON\*  
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF  
FRACTURE TREATMENT  
SHOOTING OR ACIDIZING  
(Other)

REPAIRING WELL  
ALTERING CASING  
ABANDONMENT\*

Testing zones

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 10/9/87 PBTD @ 9715, w/TOC @ 3900 Ft.  
Perforate 8834-38, Acidize w/500 gals 15% SRA, Swab Test.
- 10/12/87 Set CIBP @ 8827, Perforate 8813-20 & acidize w/500 gals 15% SRA, Swab Test.
- 10/14/87 Set retainer @ 8807, Squeeze perms w/100 sks Class "H", Perforate 8773-95, Acidize w/500 gals 20% SRA, Swab test.
- 10/22/87 Set retainer @ 8768, Squeeze perms w/100 sks Class "H", Perforate 8747-56 & 8698-8716, Acidize w/500 gals 20% SRA, Swab test.
- 10/23/87 Acidize w/5000 gals 20% SRA & ball sealers, Swab test.

ACCEPTED FOR RECORD

SJS

CHANDLER, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED NM Young NM Young TITLE Drilling Superintendent DATE Oct. 30, 1987

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side