

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. <b>30-025-30072</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <b>B-2229</b>
7. Lease Name or Unit Agreement Name <b>PHILMEX</b>
8. Well No. <b>29</b>
9. Pool name or Wildcat <b>MALJAMAR GB/SA</b>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>4158' GR</b>

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
**Phillips Petroleum Company**

3. Address of Operator  
**4001 Penbrook Street, Odessa, TX 79762**

4. Well Location  
Unit Letter **F** : **1980** Feet From The **NORTH** Line and **1980** Feet From The **WEST** Line

Section **27** Township **17 S** Range **33 E** NMPM **LEA** County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: **TEMPORARILY ABANDON WELLBORE** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/31/95 RU DDU UNSEAT SUCKER ROD PUMP AND POOH WITH PUMP AND RODS. INSTALL BOP. POOH W/TUBING. WIH W/ CIBP ON 2-3/8" TUBING TO DEPTH OF 4100'. SET CIBP.  
2/01/95 TEST TO 500 PSI FOR 30 MIN. TEST WAS WITNESSED BY REP OF NMCD. POOH WITH 2-3/8" TUBING. REMOVE BOP AND INSTALL WELLHEAD AND TOP FLANGE. RD DDU. TA'D WELLBORE.

This Approval of Temporary  
Abandonment Expires 2-1-2000

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *L. M. Sanders* TITLE **SUPERVISOR, REG. AFFAIRS** DATE **02/07/95**

TYPE OR PRINT NAME **L. M. SANDERS** TELEPHONE NO. **915/368-1488**

(This space for State Use)  
ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE **02-07-1995**  
CONDITIONS OF APPROVAL, IF ANY:

PRINTED IN U.S.A.

PHILMEX #29

1-30-45

TEJAS

BR-2221  
8 C-1000.8

*P. Hill*

DAY

NIGHT